



B.F. Day Elementary School

Landmarks Preservation Board Briefing Packet
February 28, 2025


Briefing #1 Recap


Existing Windows

Proposed Windows

Window Details

Overview of Existing Concrete Conditions







LANDMARK DESIGNATION


The features of the Landmark to be preserved include:

“Entire exterior of school building and site.”





**1892 BUILDING
VIEW FROM SOUTHEAST**



**1892 + 1902 BUILDINGS
VIEW FROM SOUTHEAST**




**AERIAL VIEW FROM WEST SHOWING
1916 ADDITIONS**



VIEW FROM SOUTHEAST

EXISTING WINDOW CONDITION



EAST ELEVATION



WEST ELEVATION

Window Condition Summary
 (2) openings in good condition
 (55) in moderate condition
 (128) in poor condition

LEGEND

- **Surface Defects**
 Operationally sound, routine maintenance required
- **Moderate Condition**
 Operable, physical deterioration requiring stabilization
- **Poor Condition**
 Not operable, advanced deterioration, splices and/or parts replacement required
- **Evaluation team not able to access window**

COMMON DEFICIENCIES



Separation between stile and bottom rail



Dry rot at intersection of muntins and sash



1916 tilt hardware in very bad condition



Advanced wood rot at sills



Deteriorated/partially missing parting bead




Exterior paint failure resulting in weathered bare wood at frame and sill

Maintain Compatibility with Landmark Designation


**Long Term Investment:
Energy, Operability, and Safety**

Improve the Learning Environment


EXTERIOR ELEVATIONS




EAST ELEVATION



NORTH ELEVATION



WEST ELEVATION



SOUTH ELEVATION

Basis of Design

- Aluminum clad wood historic replacement windows
- Propose Kolbe Windows Ultra Series XL Crank-Out Awning Windows as Basis of Design
- Double glazed insulated glazing units with simulated divided lites

Design Intent

- Maintain the size, proportions, and overall appearance of the historic windows
- Prioritize safe user experience in window operation
 - Crank-out awning operation with heavy duty hardware

Project Outcomes

- Extend the life of the building
- Improve building energy performance and improve thermal comfort of occupants
- Allow teachers and staff to safely operate and secure all windows
- Reduce maintenance with aluminum clad wood window units

PROMINENT EXISTING WINDOW TYPES



1892 DOUBLE HUNG WINDOW

- Stone head and sill conditions
- Brick jamb conditions




1902 DOUBLE HUNG WINDOW

- Stone head and sill conditions
- Brick jamb conditions




1916 AWNING WINDOW

- Concrete and stone head and sill conditions
- Concrete and brick jamb conditions




EXISTING AWNING WINDOW



PROPOSED AWNING WINDOW



EXISTING AWNING WINDOW




PROPOSED AWNING WINDOW

PROJECTED AWNING REPLACEMENT




EXISTING DOUBLE HUNG WINDOW




PROPOSED AWNING WINDOW

PROJECTED AWNING REPLACEMENT


WINDOW DETAILS




1916 MUNTIN




1892/1902 MUNTIN




**PROPOSED
SIMULATED DIVIDED LITE**









**1916 EXISTING
AWNING CONDITION**



**1892/1902 EXISTING
DOUBLE HUNG CONDITION**



PROPOSED



CONDITION OF EXISTING CONCRETE

Concrete deterioration has been temporarily stabilized. Repair procedures are being developed and will be proposed at a future briefing.



Questions & Discussion



Thank You