

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	8/26/2024	8/26/2024	MS4 inspection or screening: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going.	Yes, Notified Ecology	7101 m l king jr way s	Seattle	98118	47.538461	-122.283065	Other: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going.	Unconfirmed, unspecified, or not identified: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going.	Not applicable: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going.	Other: dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going.	Complaint. dry weather screening results found a fecal trigger in the ms4. further source tracing found the issue was not on going.
WAR044503	10/28/2024	10/28/2024	Pollution hotline (phone, web, app): approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4.	Yes, No Notice Required	65 s washington st	Seattle	98104	0	0	Food-related oil/grease: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4.	Other accident/spill: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4.	Not applicable: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4.	Clean-up: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. , Referred to other agency or department: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4. , Other: approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4.	approximately two gallons of cooking oil spilled onto sidewalk. cleaned up by sdot. no impact to ms4.
WAR044503	6/5/2024	6/5/2024	Direct report to your staff: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck.	Yes, No Notice Required	nfa_spills 7507 38th ave ne	Seattle		0	0	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck.	Vehicle-related business: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck.	Not applicable: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck.	nfa_spills, Clean-up: spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck.	spill of hydraulic oil to pavement from a garbage truck. no drainage impact. responsible party completed a cleanup with absorbents and a sweeper truck.
WAR044503	2/27/2024	2/27/2024	Direct report to your staff: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4.	Yes, No Notice Required	3845 aurora ave n	Seattle	98103	0	0	Sediment/soil: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4.	Other: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4.	Not applicable: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4.	Other: report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4.	Complaint. report of flooding. i found two private inlets that were full of sediment and property owner will have them cleaned. no impact to ms4.
WAR044503	7/9/2024	7/9/2024	Pollution hotline (phone, web, app): commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted.	Yes, Notified Ecology	4500 west marginal way sw	Seattle	98106	47.563193	-122.350679	Fuel and/or vehicle related fluids: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted.	Vehicle-related business: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted.	Not applicable: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted.	Clean-up: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted. , Other: commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted.	commerial vehicle leaked two gallons of hydraulic fluid onto pavement and into cb. responsible party cleaned up and disposed of waste. ms4 impacted.
WAR044503	11/21/2024	11/21/2024	Pollution hotline (phone, web, app): self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Yes, Notified Ecology	9075 51st ave ne	Seattle		0	0	Fuel and/or vehicle related fluids: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Other accident/spill: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Not applicable: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Clean-up: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. , Referred to other agency or department: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact. , Other: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.
WAR044503	8/12/2024	8/12/2024	Pollution hotline (phone, web, app): coolant reported impacting pavement. clean up complete. no impact to ms4. nfa.	Yes, Notified Ecology	35th ave w & mcgraw st	Seattle	98199	47.639548	-122.402388	Fuel and/or vehicle related fluids: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa.	Other accident/spill: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa.	Not applicable: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa.	Clean-up: coolant reported impacting pavement. clean up complete. no impact to ms4. nfa.	coolant reported impacting pavement. clean up complete. no impact to ms4. nfa.
WAR044503	7/15/2024	7/15/2024	Pollution hotline (phone, web, app): report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4.	Yes, Notified Ecology	1415 broadway	Seattle	98122	47.613179	-122.321227	Food-related oil/grease: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4.	Other accident/spill: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4.	Not applicable: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4.	Other: report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4.	report of restaurants not cleaning up spilled grease from grease bins. no impact to ms4.
WAR044503	4/16/2024	4/16/2024	Pollution hotline (phone, web, app): electrical vault thought to contain oil with pcb pumped to a private drain. pcbs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact.	Yes, Notified Ecology	13285 15th ave ne	Seattle	98125	47.725398	-122.313167	Fuel and/or vehicle related fluids: electrical vault thought to contain oil with pcb pumped to a private drain. pcbs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact.	Other accident/spill: electrical vault thought to contain oil with pcb pumped to a private drain. pcbs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact.	Not applicable: electrical vault thought to contain oil with pcb pumped to a private drain. pcbs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact.	Clean-up: electrical vault thought to contain oil with pcb pumped to a private drain. pcbs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact. , Other: electrical vault thought to contain oil with pcb pumped to a private drain. pcbs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact.	electrical vault thought to contain oil with pcb pumped to a private drain. pcbs were confirmed to be absent. slight amount of oil may have discharged to the creek but was negligible. spiller cleaned up and disposed of waste. no ms4 impact.
WAR044503	9/9/2024	9/9/2024	Pollution hotline (phone, web, app): undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted.	Yes, No Notice Required	5309 22nd ave nw	Seattle	98107	47.667013	-122.385029	Food-related oil/grease: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted.	Intentional dumping: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted.	Not applicable: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted.	Clean-up: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted. , Education/technical assistance: undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted.	undetermined amount of grease spilled into row, inlet and cb due to vandalism. grease hauler hired contractor for cleanup. ms4 impacted.
WAR044503	7/31/2024	7/31/2024	Pollution hotline (phone, web, app): commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4.	Yes, Notified Ecology	sw spokane st / delridge way sw	Seattle	98106	47.572094	-122.360020	Fuel and/or vehicle related fluids: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4.	Vehicle-related business: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4.	Not applicable: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4.	Clean-up: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4. , Other: commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4.	commercial vehicle spilled one gallon of coolant onto pavement due to mechanical failure. responsible party cleaned it up using absorbent granular and mechanical sweeper to clean up the absorbent granular. no impact to ms4.
WAR044503	6/2/2024	6/2/2024	Pollution hotline (phone, web, app): spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond.	Yes, No Notice Required	3919 18th ave w	Seattle	98119	47.655611	-122.380643	Fuel and/or vehicle related fluids: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond.	Intentional dumping: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond.	Not applicable: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond.	Clean-up: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. , Referred to other agency or department: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond. , Other: spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond.	spill of fuel at port of Seattle property. uscg and ecology responded and notified property owner. ecology stated spu did not need to respond.
WAR044503	5/29/2024	5/29/2024	Business inspection: report of over two dozen tires dumped into thorton creek. referred to parks department who will remove them. no impact to ms4.	Yes, No Notice Required	lake city way ne & ravenna ave ne	Seattle	98115	47.696228	-122.305747	Solid waste/trash: report of over two dozen tires dumped into thorton creek. referred to parks department who will remove them. no impact to ms4.	Intentional dumping: report of over two dozen tires dumped into thorton creek. referred to parks department who will remove them. no impact to ms4.	Not applicable: report of over two dozen tires dumped into thorton creek. referred to parks department who will remove them. no impact to ms4.	Referred to other agency or department: report of over two dozen tires dumped into thorton creek. referred to parks department who will remove them. no impact to ms4. , Other: report of over two dozen tires dumped into thorton creek. referred to parks department who will remove them. no impact to ms4.	Complaint. report of over two dozen tires dumped into thorton creek. referred to parks department who will remove them. no impact to ms4.
WAR044503	2/15/2024	2/15/2024	Pollution hotline (phone, web, app): vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted.	Yes, No Notice Required	38th ave s / s andover st	Seattle		47.567922	-122.285061	Fuel and/or vehicle related fluids: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted.	Vehicle collision: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted.	Not applicable: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted.	Clean-up: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted. , Other: vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted.	vehicle accident spilled antifreeze to roadway. spill was cleaned up with absorbents. no drains were impacted.
WAR044503	2/6/2024	2/6/2024	Pollution hotline (phone, web, app): report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program.	Yes, No Notice Required	4553 university way ne	Seattle	98105	47.662789	-122.313414	Food-related oil/grease: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program.	Unconfirmed, unspecified, or not identified: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program.	Not applicable: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program.	Other: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program. , Other: report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program.	Complaint. report of a used cooking oil container leak. spu located oil on the pavement and a private sanitary drain in a shared solid waste storage area and observed no ms4 impact. location referred internally to the business inspection program.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	7/13/2024	7/13/2024	Pollution hotline (phone, web, app): received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified.	Yes, Notified Ecology	1930 pike pl	Seattle	98101	47.610418	-122.343147	Other: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified.	Vehicle collision: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified.	Not applicable: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified.	Other: received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified.	received a report about a motor vehicle accident causing fluids to enter a drain, arrived on site and pavement was already cleaned up, it looks like a tiny bit made it to an inlet but was cleaned with absorbent. d/s cb was not impacted. ecology notified.
WAR044503	4/12/2024	4/12/2024	Pollution hotline (phone, web, app): truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted.	Yes, No Notice Required	2315 30th ave w	Seattle	98199	47.639190	-122.395685	Fuel and/or vehicle related fluids: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted.	Vehicle-related business: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted.	Not applicable: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted.	Clean-up: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted. Other: truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted.	truck leaked hydraulic fluid to the street. responsible party cleaned up the spill. no drains impacted.
WAR044503	3/24/2024	3/24/2024	Pollution hotline (phone, web, app): report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party.	Yes, Notified Ecology	4127 48th ave s	Seattle	98118	47.565644	-122.273645	Fuel and/or vehicle related fluids: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party.	Construction activity: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party.	Not applicable: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party.	Clean-up: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party. Referred to other agency or department: report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party.	report of an oil spill related to a residential construction project. spu investigation found diesel impact to the row and a ms4 drain due to an accidental spill. spu deployed on hand absorbents and cleanup was completed by the responsible party.
WAR044503	4/26/2024	4/26/2024	ERTS referral: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up.	Yes, No Notice Required	water body	Seattle		47.636837	-122.333631	Fuel and/or vehicle related fluids: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up.	Other: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up.	Not applicable: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up.	Referred to other agency or department: spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up.	spu spill response received multiple calls about sinking vessel in lake union. not an ms4 issue. doe was agency responsible for assessment and follow-up actions and clean-up.
WAR044503	10/4/2024	10/4/2024	Pollution hotline (phone, web, app): report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents.	Yes, Notified Ecology	1406 e union st	Seattle	98122	47.613114	-122.313929	Fuel and/or vehicle related fluids: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents.	Vehicle collision: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents.	Not applicable: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents.	Clean-up: report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents.	report of oil impact to a storm drain due to a motor vehicle accident. sdot completed cleanup of the affected pavement. spu confirmed transmission fluid impact to an ms4 drain and completed recovery with on hand absorbents.
WAR044503	1/22/2024	1/22/2024	Pollution hotline (phone, web, app): leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures.	Yes, Notified Ecology	13525 lake city way ne	Seattle	98125	47.727174	-122.292867	Fuel and/or vehicle related fluids: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures.	Vehicle-related business: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures.	Not applicable: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures.	Clean-up: leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures.	leak of fuel from a school bus to private parking area and street. entered both private and spu drainage system. responsible party hired contractor to do cleanup and spu also placed boom in two of our structures.
WAR044503	12/27/2024	12/27/2024	Pollution hotline (phone, web, app): no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom.	Yes, Notified Ecology	s graham st & 31st ave s	Seattle	98108	47.546163	-122.292604	Fuel and/or vehicle related fluids: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom.	Vehicle collision: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom.	Not applicable: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom.	Clean-up: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom. Other: no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom.	no fluids in the road upon arrival. found 5 cups of oil in the catch basin. ms4 impacted but no impact downstream. deployed oil absorbent boom.
WAR044503	2/14/2024	2/14/2024	Direct report to your staff: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted.	Yes, Notified Ecology	12301 stone ave n	Seattle	98133	47.718839	-122.342425	Fuel and/or vehicle related fluids: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted.	Intentional dumping: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted.	Not applicable: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted.	Clean-up: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted. Other: approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted.	Complaint. approximately one quart of motor oil dumped into a spu owned cb. used on hand materials to clean cb. ms4 impacted.
WAR044503	9/16/2024	9/16/2024	Pollution hotline (phone, web, app): motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted	Yes, Notified Ecology	2425 sw barton st	Seattle	98106	47.520858	-122.364365	Fuel and/or vehicle related fluids: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted	Intentional dumping: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted	Not applicable: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted	Clean-up: motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted	motor oil found in a catch basin in separated area. presumably dumped; responsible party unknown. no evidence found that oil had made it to the stormwater mainline. spu completed cleanup. erts submitted
WAR044503	6/4/2024	6/4/2024	Pollution hotline (phone, web, app): windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill.	Yes, Notified Ecology	9025 cyrus ave nw	Seattle	98117	47.695009	-122.399060	Fuel and/or vehicle related fluids: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill.	Other: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill.	Not applicable: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill.	Clean-up: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill. Other: windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill.	windstorm knocked down transformer which spilled to the street. no pcbs present. only sheen entered an inlet, none recoverable. responsible party cleaned up the spill.
WAR044503	4/9/2024	4/9/2024	Pollution hotline (phone, web, app): chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps.	Yes, Notified Ecology	12524 10th ave nw	Seattle	98177	47.720336	-122.368732	Sediment/soil: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. Other: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps.	Construction activity: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. Other: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps.	Not applicable: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps.	Education/technical assistance: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps. Other: chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps.	chemical dumping reported. tool wash was dumped into junction box. ms4 impacted. could not see any downstream impact. business inspection done to reinforce bmps.
WAR044503	7/12/2024	7/12/2024	Pollution hotline (phone, web, app): received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary.	Yes, No Notice Required	1st ave nw & nw 132nd st	Seattle	98177	47.725062	-122.358259	Sewage/septage/pet waste/human waste: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary.	Intentional dumping: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary.	Not applicable: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary.	Other: received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary.	received a report about an rv dumping sewage. site visit confirmed the rv is no longer there, and there is brown staining where sewage once was. there was no drain impact and nothing to clean up. no further action is necessary.
WAR044503	4/26/2024	4/26/2024	ERTS referral: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4.	Yes, Notified Ecology	5228 shilshole ave nw	Seattle	98107	47.665321	-122.382858	Other: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4.	Other accident/spill: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4.	Not applicable: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4.	Other: report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4.	Complaint. report of gravel spilled in roadway. spilled material cleaned up by sdot. no impact to ms4.
WAR044503	7/18/2024	7/18/2024	Pollution hotline (phone, web, app): a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted.	Yes, No Notice Required	600 e pine st	Seattle	98122	47.615595	-122.324158	Solid waste/trash: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted.	Other accident/spill: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted.	Not applicable: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted.	Clean-up: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. Education/technical assistance: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted. Other: a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted.	a vehicle tipped over two compost bins, spilling some contents to the street. responsible party (compost bin owner) attempted to clean up spill with washwater. no drains impacted.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/26/2024	2/26/2024	Pollution hotline (phone, web, app): spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow.	Yes, No Notice Required	1st ave s / s walker st	Seattle		47.583978	-122.334209	Fuel and/or vehicle related fluids: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow.	Vehicle collision: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow.	Not applicable: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow.	Clean-up: spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow.	spu spill response received report of motor oil from motor vehicle accident spilled to road and catch basin. spu mitigated oil with hydrophobic pads and granular absorbents. erts submitted. downstream separated line checked. no odor or sheen in flow.
WAR044503	6/4/2024	6/4/2024	MS4 inspection or screening: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing.	Yes, Notified Ecology	e lynn st / fairview ave e	Seattle		47.639726	-122.329389	Other: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing.	Unconfirmed, unspecified, or not identified: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing.	Not applicable: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing.	Other: spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing.	Complaint. spu identified trigger level potassium test results in the ms4. source tracing investigation found the issue was not ongoing.
WAR044503	8/2/2024	8/2/2024	Pollution hotline (phone, web, app): spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party.	Yes, No Notice Required	1550 n 115th st	Seattle	98133	47.714247	-122.336898	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party.	Vehicle-related business: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party.	Not applicable: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party.	Clean-up: spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party.	spill of hydraulic oil to pavement on private property. no impacts to the ms4 or private drainage. spill cleanup up by responsible party.
WAR044503	8/17/2024	8/17/2024	Pollution hotline (phone, web, app): spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required.	Yes, No Notice Required	18800 orillia rd s	Seattle		0	0	Fuel and/or vehicle related fluids: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required.	Other accident/spill: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required.	Not applicable: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required.	Clean-up: spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required.	spu spill response received report of small hydraulic spill by waste hauler as a courtesy. spill occurred at transfer station outside city jurisdiction. no follow-up required.
WAR044503	8/21/2024	8/21/2024	Pollution hotline (phone, web, app): spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident.	Yes, No Notice Required	2420 westlake ave n	Seattle	98109	47.640432	-122.341344	Fuel and/or vehicle related fluids: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident.	Other accident/spill: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident.	Not applicable: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident.	Referred to other agency or department: spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident.	spu spills received report of gasoline spill to lake union, likely from boat. incident was referred to national response center. subsequent reports advised that gasoline spill was from a boat. no ms4 impacted by spill-water to water incident.
WAR044503	8/13/2024	8/13/2024	Business inspection: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4	Yes, Notified Ecology	5146 25th ave ne	Seattle	98105	47.667757	-122.300390	Food-related oil/grease: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4	Other: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4	Not applicable: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4	Clean-up: solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4	Complaint. solid lid structure showed dry staining around the pavement. investigation was conducted and responsible party informed of cleanup action that is required of them. no impact to ms4
WAR044503	12/18/2024	12/18/2024	ERTS referral: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4.	Yes, Notified Ecology	4706 sw eddy st	Seattle	98136	47.546015	-122.393004	Fuel and/or vehicle related fluids: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4.	Vehicle-related business: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4.	Not applicable: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4.	Clean-up: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4. Other: report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4.	Complaint. report of oil spill in row. found oil from possibly leaking vehicle and cleaned it up. no impact to ms4.
WAR044503	5/14/2024	5/14/2024	Direct report to your staff: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity.	Yes, Notified Ecology	4766 1st ave s	Seattle	98134	47.558775	-122.333660	Soap or cleaning chemicals: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity.	Other: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity.	Not applicable: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity.	Clean-up: company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity.	company was washing vehicles in an area that goes to the ms4. the company was instructed to stop this activity.
WAR044503	7/19/2024	7/19/2024	Pollution hotline (phone, web, app): waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted.	Yes, Notified Ecology	11038 39th ave ne	Seattle	98125	47.709492	-122.286302	Fuel and/or vehicle related fluids: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted.	Vehicle-related business: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted.	Not applicable: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted.	Clean-up: waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted.	waste pickup truck leaked hydraulic oil to pavement. responsible party cleaned up the spill. no drains impacted.
WAR044503	12/27/2024	12/27/2024	Pollution hotline (phone, web, app): mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority.	Yes, Notified Ecology	1st ave bridge	Seattle		0	0	Fuel and/or vehicle related fluids: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority.	Vehicle collision: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority.	Not applicable: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority.	Referred to other agency or department: mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority.	mva on 1st ave bridge. no impact to ms4. referred to jurisdictional authority.
WAR044503	11/2/2024	11/2/2024	Pollution hotline (phone, web, app): drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa.	Yes, Notified Ecology	1011 sw klickitat way	Seattle	98134	47.569654	-122.348452	Fuel and/or vehicle related fluids: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa.	Intentional dumping: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa.	Not applicable: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa.	Referred to other agency or department: drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa.	drilled gas tank spilled onto pavement and into drain in direct discharge system. property owner coordinated clean up. no evidence of product impact downstream. no sheen on duwamish. nfa.
WAR044503	11/8/2024	11/8/2024	ERTS referral: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4.	Yes, Notified Ecology	3701 ne 45th st	Seattle	98105	47.661011	-122.288007	Food-related oil/grease: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4.	Other accident/spill: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4.	Not applicable: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4.	Clean-up: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4. Education/technical assistance: restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4.	Complaint. restaurant spilled cooking oil in parking lot and grassy area. oil is being tracked into row. placed down absorbent granules and restaurant will clean up oil. no impact to ms4.
WAR044503	1/31/2024	1/31/2024	Pollution hotline (phone, web, app): self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall.	Yes, Notified Ecology	2001 w garfield st	Seattle	98119	47.630999	-122.382825	Fuel and/or vehicle related fluids: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall.	Unconfirmed, unspecified, or not identified: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall.	Not applicable: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall.	Clean-up: self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall.	self report by port of Seattle of an unknown material spill on their property. port staff cleaned the unknown sheen from the pavement and affected port storm drain. spu site visit confirmed cleanup occurred, noted no impact to the ms4, and observed no sheen at the outfall.
WAR044503	12/16/2024	12/16/2024	ERTS referral: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup.	Yes, Notified Ecology	12347 25th ave ne	Seattle	98125	47.718908	-122.302327	Firefighting foam: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup.	Other: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup.	Not applicable: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup.	nfa_spills, Other: li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup.	Complaint. li+ battery fire caused discharge of fire fighting foam to thorton creek. no cleanup possible. business referred to stormwater business inspection program for followup.
WAR044503	10/31/2024	10/31/2024	Pollution hotline (phone, web, app): actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa.	Yes, Notified Ecology	e montlake pt e & montlake bv off rd	Seattle	98105	47.661247	-122.296650	Other: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa.	Other accident/spill: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa.	Not applicable: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa.	Referred to other agency or department: actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa.	actually referred to rp. no sign of coolant at outfall 100 yards from incident. ms4 impacted. vactor pumped down affected cb. nfa.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	3/21/2024	3/21/2024	Pollution hotline (phone, web, app): self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance.	Yes, Notified Ecology	1701 ne 96th st	Seattle	98115	47.698288	-122.309230	Fuel and/or vehicle related fluids: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. Sediment/soil: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance.	Vehicle-related business: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance.	Not applicable: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance.	Clean-up: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance. , Other: self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance.	self reported spill of hydraulic fluid from a leaking waste collection truck. initial cleanup by the responsible party. ms4 impact due to an incomplete cleanup was later cleaned by the responsible party with spu assistance.
WAR044503	10/29/2024	10/29/2024	Pollution hotline (phone, web, app): received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed.	Yes, No Notice Required	poplar pl s & s dean st	Seattle	98144	47.595446	-122.312569	Fuel and/or vehicle related fluids: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed.	Intentional dumping: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed.	Not applicable: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed.	Other: received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed.	received a report about sheen on a sidewalk. site visit located the sheen, but due to the small amount, it was unrecoverable. the road is unimproved road with no nearby drainage, therefore there is no drain impact. no further work is needed.
WAR044503	8/9/2024	8/9/2024	Pollution hotline (phone, web, app): found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa.	Yes, No Notice Required	2114 30th ave s	Seattle	98144	47.584008	-122.293760	Unconfirmed, unspecified, or not identified: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa.	Vehicle-related business: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa.	Not applicable: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa.	Clean-up: found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa.	found signs of staining from leaking van. no evidence it made it to the inlet. no impact to ms4. nfa.
WAR044503	2/7/2024	2/7/2024	Pollution hotline (phone, web, app): spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure.	Yes, Notified Ecology	12354 24th ave ne	Seattle	0	0	0	Sewage/septage/pet waste/human waste: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure.	Other accident/spill: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. , Other: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure.	Not applicable: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure.	Clean-up: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure. , Referred to other agency or department: spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure.	spu temporary pump system failure led to sewage impact to private property and thorton creek. spu restored proper pump function and implemented a beach closure procedure.
WAR044503	1/6/2024	1/6/2024	Pollution hotline (phone, web, app): received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary.	Yes, Notified Ecology	s norfolk st & martin luther king jr wy s	Seattle	98118	47.513356	-122.278919	Fuel and/or vehicle related fluids: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary.	Vehicle collision: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary.	Not applicable: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary.	Clean-up: received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary.	received a report of transformer oil entering a drain due to a downed power line pole. transformer oil did enter the ms4. the responsible party notified ecology, wemad, and hired a contractor to pressure wash the pavement and pump out the drain. no further action is necessary.
WAR044503	7/29/2024	7/29/2024	Pollution hotline (phone, web, app): self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company.	Yes, Notified Ecology	5000 fauntleroy way sw	Seattle	98136	47.557364	-122.381110	Fuel and/or vehicle related fluids: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company.	Intentional dumping: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company.	Not applicable: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company.	Clean-up: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company. , Education/technical assistance: self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company.	self report of a fuel spill due to vandalism by an unknown party. spu identified impact to a private unmapped storm drain structure but no ms4 drainage impact. cleanup was coordinated by the affected property management company.
WAR044503	9/3/2024	9/3/2024	Direct report to your staff: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned.	Yes, Notified Ecology	1st ave s / denver ave s	Seattle	98146	47.561211	-122.334213	Other: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned.	Other accident/spill: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. , Intentional dumping: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned.	Not applicable: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned.	Clean-up: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned. , Other: white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned.	white paint that is non recoverable has entered into the cb. ms4 impacted. put in work order to have cb cleaned.
WAR044503	4/28/2024	4/28/2024	Pollution hotline (phone, web, app): report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4.	Yes, No Notice Required	sw admiral way/63rd ave sw	Seattle	98116	47.575917	-122.413460	Fuel and/or vehicle related fluids: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4.	Vehicle collision: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4.	Not applicable: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4.	Referred to other agency or department: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4. , Other: report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4.	report of vehicle fluids in roadway from vehicle accident. referred to sdot. no impact to ms4.
WAR044503	12/30/2024	12/30/2024	Pollution hotline (phone, web, app): home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak.	Yes, Notified Ecology	5029 harold pl ne	Seattle	98105	47.665484	-122.272097	Fuel and/or vehicle related fluids: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak.	Vehicle-related business: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak.	Not applicable: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak.	Clean-up: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak. , Other: home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak.	home heating oil reported leaking to ms4. found motor oil leaking from residents vehicle into ms4. no downstream impact. boom and drip tray was placed to prevent further impacts. resident to fix vehicle leak.
WAR044503	2/13/2024	2/13/2024	Pollution hotline (phone, web, app): received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation.	Yes, No Notice Required	1st ave ne / ne 100th st	Seattle	98115	47.701362	-122.328512	Fuel and/or vehicle related fluids: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation.	Vehicle collision: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation.	Not applicable: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation.	Clean-up: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation. , Other: received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation.	received a report of a semi truck crash on i-5 releasing 50 gallons of diesel to the freeway drains. we located where the diesel left the drainage system and entered thorton creek. deployed boom around the outfall, and soaked up some of the diesel with pads. ecology already knows of the situation.
WAR044503	9/26/2024	9/26/2024	Pollution hotline (phone, web, app): caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable.	Yes, Notified Ecology	3323 walingford ave n	Seattle	98103	47.647334	-122.336721	Fuel and/or vehicle related fluids: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable.	Unconfirmed, unspecified, or not identified: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable.	Not applicable: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable.	Clean-up: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable. , Other: caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable.	caller reported gasoline spill from unknown source. gasoline entered an inlet and catch basin and was cleaned up with oil absorbent materials. a work order was initiated to have the structure more thoroughly cleaned. gasoline did enter the outlet pipe from the catch basin but was an insignificant amount that was not recoverable.
WAR044503	12/20/2024	12/20/2024	Pollution hotline (phone, web, app): report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted.	Yes, Notified Ecology	2540 westlake ave n	Seattle	98109	47.643160	-122.343248	Fuel and/or vehicle related fluids: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted.	Vehicle collision: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted.	Not applicable: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted.	Clean-up: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted. , Other: report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted.	report of car accident but upon my arrival at location it was a fuel tank on a private vehicle that had been drilled. approximately five gallons of gas impacted parking lot and five gallons impacted cb. sdot cleaned parking lot and i cleaned cb. ms4 impacted.
WAR044503	8/26/2024	8/26/2024	Pollution hotline (phone, web, app): spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted.	Yes, Notified Ecology	7215 sand point way ne	Seattle	98115	47.681287	-122.264110	Fuel and/or vehicle related fluids: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted.	Intentional dumping: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted.	Not applicable: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted.	Clean-up: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted. , Other: spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted.	spu spill response dispatch to report of gasoline pooling in parking area. as courtesy spu spill placed hydrophobic booms to mitigate spill. advised property manager to properly dispose of waste. erts was filed by reporting party. ms4 not impacted.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	3/28/2024	3/28/2024	Pollution hotline (phone, web, app): spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4.	Yes, No Notice Required	28700 se 252nd pl	ravensdale	98038	47.376039	-121.961887	Fuel and/or vehicle related fluids: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4.	Vehicle-related business: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4.	Not applicable: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4.	Clean-up: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4., Other: spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4.	spu spill response responded to 5 gallon spill of hydraulic fluid at landsburg operation center. spill was cleaned from catch basins and gravel by professional contractor. no impact to receiving waterbody. erts was filed due to impact to infiltration catch basins thus ms4.
WAR044503	6/11/2024	6/11/2024	Pollution hotline (phone, web, app): report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4.	Yes, No Notice Required	2425 sw webster st	Seattle	98106	47.534758	-122.364701	Fuel and/or vehicle related fluids: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4.	Vehicle-related business: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4.	Not applicable: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4.	Clean-up: report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4.	report of vehicle leaking, called reporting party and she said vehicle owners are working on vehicles and fluid is entering into drain. found one cup of motor oil on pavement that i cleaned up using granular. no spu assets impacted. no impact to ms4.
WAR044503	9/30/2024	9/30/2024	Pollution hotline (phone, web, app): side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral.	Yes, No Notice Required	9020 35th ave sw	Seattle	98126	47.522119	-122.376355	Sewage/septage/pet waste/human waste: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral.	Other accident/spill: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral.	Not applicable: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral.	Clean-up: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral., Clean-up: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral., Referred to other agency or department: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral., Other: side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral.	side sewer was obstructed and overflowing onto a private parking lot. sewage did not leave the property, the ms4 was not impacted. responsible party hired a plumber to clear the lateral.
WAR044503	7/23/2024	7/23/2024	Pollution hotline (phone, web, app): report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4.	Yes, No Notice Required	4247 greenwood ave n	Seattle	98103	47.659055	-122.355722	Other: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4.	Unconfirmed, unspecified, or not identified: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4.	Not applicable: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4.	Other: report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4.	report of paint spilled into drainage, drywall mud spilled on street next to inlet. no impact to ms4.
WAR044503	1/5/2024	1/5/2024	Pollution hotline (phone, web, app): received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary.	Yes, Notified Ecology	7109 18th ave sw	Seattle	98106	47.538803	-122.353342	Fuel and/or vehicle related fluids: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary.	Vehicle-related business: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary.	Not applicable: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary.	Clean-up: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary., Other: received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary.	Complaint, received a report of a leaking vehicle with automobile fluids entering a drain. site visit confirmed transmission fluid entered the ms4. i put boom in the cb and notified ecology and wemd. boom was left in the cb until the leaking vehicle was fixed. no further action is necessary.
WAR044503	7/26/2024	7/26/2024	Pollution hotline (phone, web, app): self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Yes, Notified Ecology	ne 125th st & 38th ave ne	Seattle	98125	47.719223	-122.287344	Fuel and/or vehicle related fluids: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Vehicle-related business: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Not applicable: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Clean-up: self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	self reported coolant spill from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.
WAR044503	1/26/2024	1/26/2024	Pollution hotline (phone, web, app): spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdc and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet.	Yes, No Notice Required	3012 nw 63rd st	Seattle	98107	47.674695	-122.396350	Sediment/soil: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdc and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet.	Construction activity: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdc and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet.	Not applicable: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdc and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet.	Education/technical assistance: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdc and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet., Other: spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdc and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet.	spu spills received a report of sediment and oil leaving construction site. no active discharge discovered during site visit. referred issue to sdc and advised project manager to implement proper erosions and site management. no erts submitted no apparent impact to downstream inlet.
WAR044503	1/29/2024	1/29/2024	Pollution hotline (phone, web, app): spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil.	Yes, No Notice Required	8602 12th ave sw	Seattle	98106	47.526327	-122.350275	Fuel and/or vehicle related fluids: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil.	Intentional dumping: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil.	Not applicable: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil.	Clean-up: spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil.	spu spills was dispatched to report of 5 quarts of in curblin. spu cleaned spill with on-hands materials. ertsed issue even though no signs of sheen in ds cb as spilled material was motor oil. placed precautionary boom in same cb. check furthers ds drainage mainline no evidence motor oil.
WAR044503	5/31/2024	5/31/2024	ERTS referral: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4.	Yes, Notified Ecology	10409 aurora ave n	Seattle	98133	47.704617	-122.345067	Fuel and/or vehicle related fluids: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4.	Vehicle-related business: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4.	Not applicable: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4.	Referred to other agency or department: investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4.	Complaint, investigated the area of complaint. referred to sdot. placed onion sack in spu cb. no impact to ms4.
WAR044503	6/20/2024	6/20/2024	Pollution hotline (phone, web, app): received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly.	Yes, No Notice Required	722 n 95th st	Seattle	98103	47.698018	-122.348805	Fuel and/or vehicle related fluids: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly.	Vehicle-related business: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly.	Not applicable: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly.	Clean-up: received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly.	received a spill report of a truck leaking hydraulic fluid. responsible hired a contractor to clean the spill, site visit confirmed there was no drain impact and it had been cleaned up properly.
WAR044503	4/27/2024	4/27/2024	Pollution hotline (phone, web, app): report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4.	Yes, No Notice Required	delridge way sw / sw andover st	Seattle	98106	47.568346	-122.363293	Other: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4.	Vehicle-related business: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4.	Not applicable: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4.	Clean-up: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4., Other: report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4.	report of commercial vehicle that accidentally spilled one gallon of coolant onto pavement. spiller cleaned up and disposed of waste. no impact to ms4.
WAR044503	6/23/2024	6/23/2024	Pollution hotline (phone, web, app): report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains.	Yes, No Notice Required	410 broadway e	Seattle	98102	47.622446	-122.320612	Sewage/septage/pet waste/human waste: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains.	Unconfirmed, unspecified, or not identified: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains.	Not applicable: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains.	Clean-up: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains., Other: report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains.	report of sewage coming up through crack in road. investigated site-- puddle of liquid on curb, less than gallon. liquid has been cleaned, no impact to drains.
WAR044503	2/21/2024	2/21/2024	Pollution hotline (phone, web, app): grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa	Yes, Notified Ecology	9999 holman rd nw	Seattle	98177	47.701899	-122.363749	Food-related oil/grease: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa	Other accident/spill: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa	Not applicable: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa	Clean-up: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa. Clean-up: grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa.	grease was spilled into a private drainage system and made its way into the ms4. property manager hired a contractor to clean which was completed 2/21. nfa

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	11/26/2024	11/26/2024	ERTS referral: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed.	Yes, Notified Ecology	5029 harold pl ne	Seattle	98105	47.665484	-122.272097	Fuel and/or vehicle related fluids: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed.	Unconfirmed, unspecified, or not identified: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed.	Not applicable: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed.	Other: report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed.	Complaint. report of a recurring sheen discharge from a private drainage system. spu observed sheen on the pavement, deployed absorbent in the potentially impacted storm drain, and requested the property owner to work to resolve the issue. no ms4 drain impact observed.
WAR044503	6/20/2024	6/20/2024	Direct report to your staff: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions.	Yes, Notified Ecology	2400 westlake ave n	Seattle	98109	47.639747	-122.340910	Fuel and/or vehicle related fluids: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions.	Unconfirmed, unspecified, or not identified: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions.	Not applicable: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions.	Referred to other agency or department: spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions.	spu spill responders encounter sheen in towards the middle on lake union during boat training, checked nearby spu outfalls and marinas, no evidence of sheen. referred to doe via erts. advised doe spill responder of my actions.
WAR044503	4/16/2024	4/16/2024	Pollution hotline (phone, web, app): report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris.	Yes, No Notice Required	14115 aurora ave n	Seattle	98133	47.731405	-122.345805	Other: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris.	Vehicle-related business: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris.	Not applicable: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris.	Other: report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris.	report of leaking rv into a drain. no clear evidence that other than minor drips entered the drain. asked sdot to sweep the road to remove soil and debris.
WAR044503	8/2/2024	8/2/2024	Pollution hotline (phone, web, app): a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4.	Yes, Notified Ecology	12028 31st ave ne	Seattle	98125	47.716332	-122.294928	Fuel and/or vehicle related fluids: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4.	Intentional dumping: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4.	Not applicable: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4.	Clean-up: a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4.	a small amount of used motor oil found spilled to pavement and soil at the back of a property near an alleyway. spu completed clean up using pads and removed soil and gravel as well. no drains nearby - no impact to ms4.
WAR044503	1/20/2024	1/20/2024	Pollution hotline (phone, web, app): rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken.	Yes, No Notice Required	n 143rd st / fremont ave n	Seattle	98133	47.732313	-122.350492	Firefighting foam: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken.	Other: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken.	Not applicable: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken.	Other: rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken.	rv fire on side of street with fire fighting foam being used to put out fire. foam ended up going to spu biofiltration swale system. no cleanup undertaken.
WAR044503	9/11/2024	9/11/2024	Pollution hotline (phone, web, app): spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup.	Yes, No Notice Required	39th ave ne & ne 110th st	Seattle	98125	47.708325	-122.286751	Fuel and/or vehicle related fluids: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup.	Vehicle-related business: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup.	Not applicable: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup.	nfa_spills, Clean-up: spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup.	spill of hydraulic oil to pavement and spu infrastructure from commercial garbage truck. no impacts to relieving waters. responsible party hired a private contractor to conduct the cleanup.
WAR044503	11/27/2024	11/27/2024	Pollution hotline (phone, web, app): report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa.	Yes, Notified Ecology	7th ave s & monroe st	Seattle	98108	47.531259	-122.325518	Fuel and/or vehicle related fluids: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa.	Unconfirmed, unspecified, or not identified: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa.	Not applicable: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa.	Other: report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa.	report of sheen over 4 blocks of street was 3 days old by time referred to spill response. small amount of sheen seen in about 4 different spu catch-basins considered unrecoverable. ms4 system. nfa.
WAR044503	10/7/2024	10/7/2024	ERTS referral: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted.	Yes, Notified Ecology	4659 25th ave ne	Seattle	98105	0	0	Other: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted.	Other: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted.	Not applicable: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted.	Clean-up: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted. Other: oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted.	Complaint, oil from a leaking dumpster entered into a nearby cb. responsible party cleaned cb and installed a fabric filter, trash bins have been permanently relocated. ms4 impacted.
WAR044503	1/7/2024	1/7/2024	Pollution hotline (phone, web, app): received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary.	Yes, Notified Ecology	23rd ave / e yesler way	Seattle	98122	47.601666	-122.302349	Fuel and/or vehicle related fluids: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary.	Vehicle-related business: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary.	Not applicable: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary.	Clean-up: received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary.	received a report of a hydraulic spill due to mechanical failure of a truck. about 40 gallons was released to pavement. the responsible party sent me pictures and confirmed there was no ms4 impact. they hired a contractor to pressure wash the pavement. no further action is necessary.
WAR044503	12/16/2024	12/16/2024	Pollution hotline (phone, web, app): report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted.	Yes, Notified Ecology	4700 50th ave s	Seattle	98118	0	0	Other: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted.	Intentional dumping: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted.	Not applicable: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted.	Clean-up: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted. Other: report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted.	Complaint. report of food waste dumped in cb. eggs and other food waste found in cb and i removed it. ms4 impacted.
WAR044503	10/31/2024	10/31/2024	Pollution hotline (phone, web, app): petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa.	Yes, Notified Ecology	15th ave s / s holgate st	Seattle	47.586361	-122.313373	Other: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa.	Unconfirmed, unspecified, or not identified: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa.	Not applicable: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa.	Other: petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa.	petroleum odor reported, and after source tracing, no fluids or cause of problem was found. ms4 impacted by odor. nfa.	
WAR044503	4/6/2024	4/6/2024	Pollution hotline (phone, web, app): gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4.	Yes, No Notice Required	5601 rainier ave s	Seattle	98118	47.551803	-122.278329	Unconfirmed, unspecified, or not identified: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Other wastewater: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Other accident/spill: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4.	Unconfirmed, unspecified, or not identified: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Other accident/spill: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4.	Not applicable: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4.	Education/technical assistance: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Education/technical assistance: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Referred to other agency or department: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4. Other: gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4.	gray water reported in separated area. found broken sanitary yard drains circulating water. referred to wastewater source control to help restaurants implement bmps. no impact to ms4.
WAR044503	7/18/2024	7/18/2024	Pollution hotline (phone, web, app): report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead.	Yes, No Notice Required	3600 s judkins st	Seattle	98144	47.592223	-122.287312	Sewage/septage/pet waste/human waste: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead.	Unconfirmed, unspecified, or not identified: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead.	Not applicable: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead.	Other: report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead.	Complaint. report of toilet paper on bulkhead. got a slight ammonia hit on an ammonia test, but no other definitive proof that sewage is on the bulkhead.
WAR044503	7/22/2024	7/22/2024	MS4 inspection or screening: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing.	Yes, Notified Ecology	s kenyon st & 39th ave s	Seattle	98118	47.531541	-122.283203	Other: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing.	Unconfirmed, unspecified, or not identified: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing.	Not applicable: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing.	Other: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing. Other: spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing.	Complaint. spu identified trigger level fluoride test results in the ms4. follow up source tracing investigation found the issue was not ongoing.
WAR044503	2/8/2024	2/8/2024	Pollution hotline (phone, web, app): spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public.	Yes, Notified Ecology	102 n 132nd st	Seattle	98133	47.725577	-122.357813	Sewage/septage/pet waste/human waste: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public.	Intentional dumping: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public.	Not applicable: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public.	Education/technical assistance: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public. Other: spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public.	spu spills responded to report of rv illegally dumping sewage in private parking lot. property manager cleaned spill. no drains impact, but erts was filed as sewage was somewhat accessible to public.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	6/28/2024	6/28/2024	Pollution hotline (phone, web, app): please see 166157	Yes, No Notice Required	4611 shilshole ave nw	Seattle	98107	47.661662	-122.379343	Fuel and/or vehicle related fluids: please see 166157	Other accident/spill: please see 166157	Not applicable: please see 166157	Referred to other agency or department: please see 166157	please see 166157
WAR044503	11/13/2024	11/13/2024	Pollution hotline (phone, web, app): report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered.	Yes, No Notice Required	9215 34th ave sw	Seattle	98126	47.520498	-122.375761	Fuel and/or vehicle related fluids: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered.	Intentional dumping: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered.	Not applicable: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered.	Clean-up: report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered.	report of gasoline spilled from pickup truck with drilled gas tank. vehicle towed and captured gasoline removed from site. approx 1 gallon of gasoline may have went to ms4 and could not be recovered.
WAR044503	1/27/2024	1/27/2024	Pollution hotline (phone, web, app): spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek.	Yes, No Notice Required	12354 24th ave ne	Seattle	0	0	0	Sewage/septage/pet waste/human waste: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek.	Other accident/spill: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek.	Not applicable: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek.	Referred to other agency or department: spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek.	spu spill responder dispatched to report of sewage going into thorton creek. sewage was issuing from spu sewage mainline, flowing overland through private yards and discharging into the creek. all relevant regulatory reporting and posting was undertaken. erts submitted. all sewage was inevitably diverted via trench to nearby king county metro sewage mainline maintenance hole, thus stopping impact to thorton creek.
WAR044503	11/13/2024	11/13/2024	Pollution hotline (phone, web, app): side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up	Yes, Notified Ecology	5040 9th ave ne	Seattle	0	0	0	Sewage/septage/pet waste/human waste: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up	Other accident/spill: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up	Not applicable: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up	Referred to other agency or department: side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up	side sewer blockage at a school forced sewage surfacing along the right of way which flowed along the curbline and back into a combined sanitary mainline. no sewage impacts to ms4. case referred to wwscc for follow-up
WAR044503	11/27/2024	11/27/2024	Pollution hotline (phone, web, app): found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping.	Yes, Notified Ecology	8th ave nw & nw 63rd st	Seattle	98107	47.674535	-122.366092	Fuel and/or vehicle related fluids: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping.	Intentional dumping: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping.	Not applicable: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping.	Clean-up: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping. Referred to other agency or department: found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping.	found small motor was dumped on the side of the road leaking oil into the street and ms4. absorbents and pads were placed. no sheen observed downstream. engine bagged and sealed and removed by illegal dumping.
WAR044503	4/16/2024	4/16/2024	Direct report to your staff: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted.	Yes, No Notice Required	13285 15th ave ne	Seattle	98125	47.725398	-122.313167	Fuel and/or vehicle related fluids: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted.	Other accident/spill: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted.	Not applicable: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted.	Clean-up: spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted.	spill response company was cleaning out an underground vault that contained a small amount of transformer oil had equipment failure. the truck had a drain cap fall off the truck and the contents of the vactor spilled to pavement and thorton creek. spiller activated cleanup. spu supplied additional supplies. no ms4 impacted.
WAR044503	2/1/2024	2/1/2024	ERTS referral: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4.	Yes, Notified Ecology	582 s riverside dr	Seattle	98108	47.535594	-122.326631	Other: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4.	Vehicle-related business: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4.	Not applicable: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4.	Other: report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4.	Complaint, report of 30 gallons of hydraulic fluid spilled onto pavement. upon my arrival, fluid had already been cleaned. no impact to ms4.
WAR044503	2/7/2024	2/7/2024	Pollution hotline (phone, web, app): received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb.	Yes, Notified Ecology	24th ave ne / ne 54th st	Seattle	0	0	0	Other: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb.	Other accident/spill: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb.	Not applicable: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb.	Clean-up: received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb.	received a report about a dark oil spill near a drain, site visit confirmed there was a spill of roofing tar, it did end up getting into a cb that drains to the ms4. i cleaned it with on hand materials and reported it to ecology and wemb.
WAR044503	5/7/2024	5/7/2024	Staff referral: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa.	Yes, Notified Ecology	3rd ave s / s holgate st	Seattle	98134	47.586159	-122.330027	Fuel and/or vehicle related fluids: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa.	Unconfirmed, unspecified, or not identified: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa.	Not applicable: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa.	Clean-up: planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa.	Complaint, planned rv remediation. inspected 10 structures and found two contaminated cbs. ms4 affected but cleaned. no downstream impact. nfa.
WAR044503	6/29/2024	6/29/2024	Direct report to your staff: found spill clean up complete after large accident. no drains involved. nfa.	Yes, Notified Ecology	s stacy st / 4th ave s	Seattle	98134	47.581892	-122.329066	Fuel and/or vehicle related fluids: found spill clean up complete after large accident. no drains involved. nfa.	Vehicle collision: found spill clean up complete after large accident. no drains involved. nfa.	Not applicable: found spill clean up complete after large accident. no drains involved. nfa.	Referred to other agency or department: found spill clean up complete after large accident. no drains involved. nfa.	found spill clean up complete after large accident. no drains involved. nfa.
WAR044503	11/27/2024	11/27/2024	ERTS referral: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa.	Yes, Notified Ecology	dayton ave n & n 143rd st	Seattle	98133	47.732313	-122.353035	Fuel and/or vehicle related fluids: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa.	Intentional dumping: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa.	Not applicable: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa.	Other: found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa.	Complaint, found odor and nonrecoverable sheen. neighbor stated that diesel tank was drilled but has since been repaired. no impact to ms4. nfa.
WAR044503	6/4/2024	6/4/2024	Staff referral: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening.	Yes, Notified Ecology	9902 rainier ave s	Seattle	0	0	0	Sewage/septage/pet waste/human waste: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening.	Construction activity: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening.	Not applicable: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening.	Clean-up: public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening.	public sewer line obstructed causing a small overflow from a private side sewer lateral into lake washington. only three properties along the shore needed to be contacted. obstruction was removed that evening.
WAR044503	12/2/2024	12/2/2024	ERTS referral: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator.	Yes, Notified Ecology	5315 tallman ave nw	Seattle	0	0	0	Fuel and/or vehicle related fluids: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator.	Vehicle-related business: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator.	Not applicable: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator.	Clean-up: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator. nfa_spills, Education/technical assistance: spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator.	spill of gasoline to an private drainage system within a parking garage. the gasoline was cleaned off the ground and pavement. initial reports stated that fuel entered a stormwater drainage but on inspection no gasoline was found in the drain inlet nor a downstream oil water separator.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	7/22/2024	7/22/2024	MS4 inspection or screening: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Yes, Notified Ecology	s kenyon st & 39th ave s	Seattle	98118	47.531541	-122.283203	Other: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Not applicable: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Other: spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Complaint. spu dry weather screening found trigger level results for potassium in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.
WAR044503	5/22/2024	5/22/2024	Pollution hotline (phone, web, app): report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4.	Yes, No Notice Required	2419 nw 65th st	Seattle	98117	47.675782	-122.388505	Fuel and/or vehicle related fluids: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4.	Vehicle-related business: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4.	Not applicable: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4.	Education/technical assistance: report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4.	Complaint. report of leaking motor vehicle. arrived and found vehicle which had leaked non recoverable spills in front of and beneath vehicle. no impact to ms4.
WAR044503	6/11/2024	6/11/2024	Pollution hotline (phone, web, app): fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact.	Yes, No Notice Required	2051 nw 60th st	Seattle	98107	47.672222	-122.384364	Fuel and/or vehicle related fluids: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact.	Intentional dumping: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact.	Not applicable: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact.	Clean-up: fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact.	fuel spill to row pavement from a private vehicle due to vandalism. contained by a passerby, stabilized by sfd, absorbent disposal by spu. no ms4 impact.
WAR044503	4/9/2024	4/9/2024	Direct report to your staff: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted.	Yes, No Notice Required	922 e pike st	Seattle	98122	47.614264	-122.319782	Food-related oil/grease: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted. Solid waste/trash: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted.	Intentional dumping: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted.	Not applicable: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted.	Clean-up: garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted.	Complaint. garbage and used cooking oil spilled onto sidewalk, street and into a cb and two inlets. restaurants owners cleaned up garbage and cooking oil in row. hired contractor to clean cb and inlets. ms4 impacted.
WAR044503	4/15/2024	4/15/2024	ERTS referral: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4.	Yes, Notified Ecology	1800 s jackson st	Seattle	98144	47.599381	-122.308760	Fuel and/or vehicle related fluids: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4.	Vehicle-related business: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4.	Not applicable: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4.	Clean-up: arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4.	Complaint. arrived at location of where oil leaked and was tracked throughout parking garage. cleanup actions are in progress by apartment complex. no impact to ms4.
WAR044503	10/3/2024	10/3/2024	Pollution hotline (phone, web, app): self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact.	Yes, Notified Ecology	1350 n 34th st	Seattle	98103	47.648797	-122.340795	Fuel and/or vehicle related fluids: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact.	Other accident/spill: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact.	Not applicable: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact.	Clean-up: self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact.	self reported hydraulic fluid spill from a waste collection company at a solid waste transfer station. cleanup by the responsible party and transfer station staff. no ms4 drain impact.
WAR044503	11/1/2024	11/1/2024	Direct report to your staff: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one.	Yes, Notified Ecology	nesbit ave n / n 88th st	Seattle		47.692372	-122.343478	Fuel and/or vehicle related fluids: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one.	Intentional dumping: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one.	Not applicable: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one.	Clean-up: spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one.	Complaint. spu source control inspector found public catch basin impacted with motor oil. oil had not migrated downstream to public drainage mainline as a pollution trap is in place. previously placed hydrophobic boom was replaced with new one.
WAR044503	7/26/2024	7/26/2024	ERTS referral: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided.	Yes, Notified Ecology	5763 s oaklawn pl	Seattle	98118	47.543277	-122.259657	Other: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided.	Other: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided.	Not applicable: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided.	Education/technical assistance: home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided.	Complaint. home pool was partially emptied to perform maintenance. homeowner was ignorant of requirements to dehalogenate and volumetric control of the pool water. technical assistance provided.
WAR044503	5/13/2024	5/13/2024	Pollution hotline (phone, web, app): report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted.	Yes, Notified Ecology	125 ne 94th st	Seattle	98115	47.696656	-122.327201	Other: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted.	Intentional dumping: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted.	Not applicable: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted.	Clean-up: report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted.	report of contractor pumping muddy water into cb. investigation found a hose leading to cb where about five gallons of muddy water had been pumped. contractor cleaned cb. ms4 impacted.
WAR044503	2/2/2024	2/2/2024	Pollution hotline (phone, web, app): spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact.	Yes, No Notice Required	7th ave s / s oregon st	Seattle		47.563053	-122.324090	Fuel and/or vehicle related fluids: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact.	Unconfirmed, unspecified, or not identified: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact.	Not applicable: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact.	Clean-up: spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact.	spill of motor oil to the right of way pavement. cleaned by spu spill response with granular absorbent. no evidence of drain impact.
WAR044503	3/22/2024	3/22/2024	Pollution hotline (phone, web, app): report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact.	Yes, No Notice Required	11030 8th ave ne	Seattle	98125	47.709896	-122.320200	Fuel and/or vehicle related fluids: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact.	Vehicle-related business: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact.	Not applicable: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact.	Clean-up: report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact.	report of motor oil spill due to private citizen performing auto repair. spu site visit found the responsible party accidentally spilled to pavement and provided them absorbents to assist in cleanup. no ms4 impact.
WAR044503	11/5/2024	11/5/2024	ERTS referral: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed.	Yes, Notified Ecology	nw 100th st/7th ave nw	Seattle		47.701504	-122.364772	Fuel and/or vehicle related fluids: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed.	Other accident/spill: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed.	Not applicable: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed.	Clean-up: spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed.	spu spill received erts of coolant spill from king county metro, no mention of drains impacted. king county mitigated spill. no site visit performed.
WAR044503	2/6/2024	2/6/2024	Pollution hotline (phone, web, app): report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party.	Yes, Notified Ecology	1300 university st	Seattle	98101	47.612725	-122.324824	Sewage/septage/pet waste/human waste: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party.	Other accident/spill: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party.	Not applicable: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party.	Clean-up: report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party.	report of sewage impact to the ms4 due to a private side sewer problem. containment and beach closure implemented by spu. side sewer function restored by the responsible party.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	12/28/2024	12/28/2024	Pollution hotline (phone, web, app): hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa.	Yes, No Notice Required	12801 aurora ave n	Seattle	98133	47.722559	-122.345377	Fuel and/or vehicle related fluids: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa.	Vehicle-related business: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa.	Not applicable: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa.	Clean-up: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa., Other: hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa.	hydraulic fluid spilled into private storm system with oil water separator. no fluid escaped the private system. no impact to city assets. contractor was hired to clean private assets. nfa.
WAR044503	3/16/2024	3/16/2024	Pollution hotline (phone, web, app): received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code.	Yes, No Notice Required	10616 marine view dr sw	Seattle	98146	47.507783	-122.387423	Fuel and/or vehicle related fluids: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code.	Construction activity: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code.	Not applicable: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code.	Clean-up: received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code.	received a report of a spill due to construction equipment. site visit confirmed hydraulic fluid was released to pavement and soil. no ms4 impact. responsible party sent a crew to and we cleaned with on hand materials. i will follow up with the company about educate them about the code.
WAR044503	9/27/2024	9/27/2024	Pollution hotline (phone, web, app): a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped.	Yes, No Notice Required	3509 ne 137th st	Seattle	98125	46.807974	-127.390431	Fuel and/or vehicle related fluids: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped.	Intentional dumping: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped.	Not applicable: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped.	Clean-up: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped., Clean-up: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped., Education/technical assistance: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped., Other: a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped.	a truck was vandalized to steal fuel. diesel leaked to the street pavement but did not enter any drains. the spill was cleaned and the leak stopped.
WAR044503	2/14/2024	2/14/2024	Direct report to your staff: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up.	Yes, No Notice Required	130 s kenyon st	Seattle	98108	47.533212	-122.333036	Other: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up.	Other accident/spill: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up.	Not applicable: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up.	Clean-up: small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up.	small spill of def at south transfer station. employee put spill sorb down to absorb the fluid. employee swept up contaminated spill sorb, bagged, tagged for hhw to pick up.
WAR044503	5/3/2024	5/3/2024	Pollution hotline (phone, web, app): an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted.	Yes, Notified Ecology	4144 university way ne	Seattle	98105	47.658136	-122.313003	Food-related oil/grease: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted.	Intentional dumping: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted.	Not applicable: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted.	Clean-up: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted., Other: an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted.	an unknown amount of cooking oil was intentionally dumped into two inlets and one mh. hired contractor for cleaning. ms4 impacted.
WAR044503	6/28/2024	6/28/2024	Pollution hotline (phone, web, app): hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa.	Yes, Notified Ecology	9131 10th ave s	Seattle	98108	47.521101	-122.320811	Fuel and/or vehicle related fluids: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa.	Other accident/spill: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa.	Not applicable: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa.	Clean-up: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa., Referred to other agency or department: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa., Other: hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa.	hydraulic fluid found spilled on roadway. spu and sdot cleaned up. sweeper dispatched. no drain involvement. nfa.
WAR044503	2/18/2024	2/18/2024	Pollution hotline (phone, web, app): car vandalized to steal gasoline. provided assistance to the owner. no drains affected.	Yes, No Notice Required	7304 51st ave ne	Seattle	98115	47.681392	-122.272671	Fuel and/or vehicle related fluids: car vandalized to steal gasoline. provided assistance to the owner. no drains affected.	Intentional dumping: car vandalized to steal gasoline. provided assistance to the owner. no drains affected.	Not applicable: car vandalized to steal gasoline. provided assistance to the owner. no drains affected.	Education/technical assistance: car vandalized to steal gasoline. provided assistance to the owner. no drains affected., Other: car vandalized to steal gasoline. provided assistance to the owner. no drains affected.	car vandalized to steal gasoline. provided assistance to the owner. no drains affected.
WAR044503	2/13/2024	2/13/2024	Staff referral: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa.	Yes, Notified Ecology	3rd ave s / s holgate st	Seattle	98134	47.586159	-122.330027	Sewage/septage/pet waste/human waste: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa.	Unconfirmed, unspecified, or not identified: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa., Intentional dumping: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa.	Not applicable: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa.	Clean-up: planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa.	Complaint. planned rv remediation. inspected 11 structures and found one with sewage. ms4 impacted. work order created to clean pump out wash down. nfa.
WAR044503	5/10/2024	5/10/2024	ERTS referral: report of commerial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted.	Yes, Notified Ecology	2401 utah ave s	Seattle	98134	47.581811	-122.335353	Other: report of commerial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted.	Vehicle-related business: report of commerial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted.	Not applicable: report of commerial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted.	Clean-up: report of commerial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted., Other: report of commerial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted.	report of commerial vehicle spilling 10 gallons of hydraulic fluid spilling mechanical problems. nine gallons spilled onto pavement. one gallon entered into cb. responsible party hired contractor for cleanup. ms4 impacted.
WAR044503	4/16/2024	4/16/2024	Pollution hotline (phone, web, app): bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew.	Yes, Notified Ecology	alaskan way / columbia st	Seattle	98104	47.602420	-122.336971	Fuel and/or vehicle related fluids: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew.	Vehicle-related business: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew.	Not applicable: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew.	Clean-up: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew., Other: bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew.	bus lost coolant to the roadway but no drains impacted. bus company cleaned up the spill with their own crew.
WAR044503	3/11/2024	3/11/2024	Pollution hotline (phone, web, app): car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found.	Yes, Notified Ecology	1400 alaskan way	Seattle	98101	47.607454	-122.340753	Fuel and/or vehicle related fluids: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found.	Vehicle collision: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found.	Not applicable: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found.	Other: car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found.	car accident caused fluid spill to street. slight impact to catch basin but no recoverable oil found.
WAR044503	6/13/2024	6/13/2024	Direct report to your staff: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal.	Yes, Notified Ecology	7242 seaweview ave nw	Seattle	98117	47.682135	-122.403613	Sewage/septage/pet waste/human waste: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal.	Intentional dumping: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal.	Not applicable: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal.	Clean-up: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal. Education/technical assistance: rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal.	rv leaking sewage to pavemnet and ms4. spill response team cleaned pavement. referred to rv ww program to help responsible party with wastewater disposal.
WAR044503	9/20/2024	9/20/2024	Pollution hotline (phone, web, app): spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste.	Yes, Notified Ecology	12330 33rd ave ne	Seattle	98125	0	0	Fuel and/or vehicle related fluids: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste.	nfa_spills, Intentional dumping: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste.	Not applicable: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste.	Clean-up: spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste.	spill of gasoline from a vandalism to a vehicle. impacts to pavement and soils. spu spill response cleaned up the spilled waste.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/29/2024	2/29/2024	ERTS referral: no impact to ms4. construction self reported to ecology called site to confirm details. nfa.	Yes, Notified Ecology	2500 lake washington blvd e	Seattle	98112	47.641708	-122.298168	Sediment/soil: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa.	Construction activity: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa.	Not applicable: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa.	Clean-up: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa., Referred to other agency or department: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa., Other: no impact to ms4. construction self reported to ecology. called site to confirm details. nfa.	Complaint. no impact to ms4. construction self reported to ecology. called site to confirm details. nfa.
WAR044503	9/19/2024	9/19/2024	Pollution hotline (phone, web, app): spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed	Yes, No Notice Required	7000 lincoln park way sw	Seattle	0	0	0	Sediment/soil: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed	Other accident/spill: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed	Not applicable: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed	Referred to other agency or department: spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed	spu spills dispatch to report of vector truck spilling sewage. scl contractor's vector truck was spilling sediment (not sewage) from back of tank. issue was referred to scl to manage contractor and clean-up. no drains impacted. no erts filed
WAR044503	2/5/2024	2/5/2024	Business inspection: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up.	Yes, No Notice Required	7777 7th ave s	Seattle	98108	47.533256	-122.325804	Fuel and/or vehicle related fluids: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up.	Other: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up.	Not applicable: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up.	Education/technical assistance: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up., Education/technical assistance: conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up.	conducted a business inspection at the property, during my visit i found unaddressed spills, no ms4 impact. i am working with the company to get their site cleaned up.
WAR044503	11/4/2024	11/4/2024	Pollution hotline (phone, web, app): report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa.	Yes, No Notice Required	8498 seawave pl nw	Seattle	98117	47.689763	-122.402253	Fuel and/or vehicle related fluids: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa.	Unconfirmed, unspecified, or not identified: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa.	Not applicable: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa.	Referred to other agency or department: report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa.	report of water to water spill contaminating beach at golden gardens. coast guard found no source and sheen was unrecoverable. no impact to ms4. nfa.
WAR044503	2/6/2024	2/6/2024	Pollution hotline (phone, web, app): report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline.	Yes, Notified Ecology	16th ave sw / sw morgan st	Seattle	47.544728	-122.354896	47.544728	Fuel and/or vehicle related fluids: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline.	Unconfirmed, unspecified, or not identified: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline.	Not applicable: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline.	Clean-up: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline., Other: report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline.	report of diesel in the road and impacting drains. spu site visit found widespread sheen impact to pavement and the vicinity ms4 drains. deployed absorbent boom to an affected drain and observed no sheen in the mainline.
WAR044503	3/27/2024	3/27/2024	Pollution hotline (phone, web, app): spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed.	Yes, No Notice Required	sw 106th st / 41st ave sw	Seattle	47.508262	-122.384299	47.508262	Fuel and/or vehicle related fluids: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed.	Unconfirmed, unspecified, or not identified: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed.	Not applicable: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed.	Other: spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed.	spu spill response dispatched to report of waste hauler dripping oil/hydraulic fluid throughout neighborhood. no drains impacted. no erts filed.
WAR044503	10/10/2024	10/10/2024	Direct report to your staff: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill.	Yes, No Notice Required	2001 w garfield st	Seattle	98119	47.630999	-122.382825	Fuel and/or vehicle related fluids: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill.	Construction activity: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill.	Not applicable: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill.	Other: construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill.	construction site on port of Seattle property had a mechanical failure on an excavator and spilled hydraulic fluid. one gallon hit puget sound. responsible party cleaned up the spill.
WAR044503	2/15/2024	2/15/2024	ERTS referral: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted.	Yes, Notified Ecology	11011 greenwood ave n	Seattle	0	0	0	Fuel and/or vehicle related fluids: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted.	Other accident/spill: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted.	Not applicable: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted.	Clean-up: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted., Other: unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted.	Complaint. unknown amount of fuel spilled from a container. pavement and public flow control catch basin were impacted. cleaned using a pad and a mesh bag. ms4 impacted.
WAR044503	10/3/2024	10/3/2024	Pollution hotline (phone, web, app): spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response.	Yes, Notified Ecology	23rd ave s & s forest st	Seattle	98144	47.577528	-122.303334	Unconfirmed, unspecified, or not identified: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response.	Unconfirmed, unspecified, or not identified: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response.	Not applicable: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response.	Clean-up: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response., Other: spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response.	spill report of motor oil. investigation discovered motor oil and an unknown hydrocarbon. waste recovered by spu spills. waste categorization and disposal managed by ecology spill response.
WAR044503	9/16/2024	9/16/2024	MS4 inspection or screening: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified.	Yes, Notified Ecology	s angeline st & 38th ave s	Seattle	98118	47.559460	-122.284942	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified.	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified.	Not applicable: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified.	Other: spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified.	Complaint. spu dry weather screening identified trigger level potassium concentration is the ms4. a source tracing investigation found the issue is no longer ongoing and a source was unable to be identified.
WAR044503	12/10/2024	12/10/2024	Pollution hotline (phone, web, app): sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wssc for completion of sewer repair.	Yes, Notified Ecology	6800 rainier ave s	Seattle	98118	47.541491	-122.271489	Sewage/septage/pet waste/human waste: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wssc for completion of sewer repair.	Other accident/spill: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wssc for completion of sewer repair.	Not applicable: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wssc for completion of sewer repair.	Clean-up: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wssc for completion of sewer repair., Clean-up: sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wssc for completion of sewer repair.	sewage spill from a blocked or broken side sewer lateral at a small apartment building. building owner hired a plumber to fix the problem. sewage entered a single catch basin but no discharge from this catch basin was observed. this was referred to wssc for completion of sewer repair.
WAR044503	12/9/2024	12/9/2024	Pollution hotline (phone, web, app): report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage.	Yes, No Notice Required	473 n 36th st	Seattle	98103	47.651600	-122.352516	Food-related oil/grease: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage., Other: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage.	Other: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage.	Not applicable: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage.	Clean-up: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage., Education/technical assistance: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage., Enforcement: report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage.	report of used cooking oil spill. a new business has moved in and this is from the previous tenant. the new business will sign up a uco contractor and take care of the waste and the spillage.
WAR044503	6/28/2024	6/28/2024	Pollution hotline (phone, web, app): responsible party provided pictures of adequate clean up. no impact to ms4. nfa	Yes, Notified Ecology	7 s idaho st	Seattle	98134	47.564499	-122.314983	Fuel and/or vehicle related fluids: responsible party provided pictures of adequate clean up. no impact to ms4. nfa	Other accident/spill: responsible party provided pictures of adequate clean up. no impact to ms4. nfa	Not applicable: responsible party provided pictures of adequate clean up. no impact to ms4. nfa	Clean-up: responsible party provided pictures of adequate clean up. no impact to ms4. nfa	responsible party provided pictures of adequate clean up. no impact to ms4. nfa
WAR044503	2/23/2024	2/23/2024	Pollution hotline (phone, web, app): spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen.	Yes, No Notice Required	4542 university way ne	Seattle	98105	47.662477	-122.312762	Fuel and/or vehicle related fluids: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen.	Intentional dumping: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen.	Not applicable: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen.	Clean-up: spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen.	spu spill response dispatched to report of gasoline in cb. gasoline was found in cb in ms4. erts was submitted. spill was mitigated with hydrophobic pads. downstream outfall was inspected, no sign of odor or sheen.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	5/1/2024	5/1/2024	ERTS referral: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4.	Yes, Notified Ecology	7277 perimeter rd s	Seattle	98108	47.536852	-122.303928	Other: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4.	Other accident/spill: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4.	Not applicable: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4.	Other: over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4.	Complaint. over fueling of commercial aircraft caused fuel to spill onto pavement and into private cb. responsible party hired contractor. no impact to ms4.
WAR044503	10/10/2024	10/10/2024	Pollution hotline (phone, web, app): waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted.	Yes, No Notice Required	805 ne 115th st	Seattle	98125	47.712030	-122.320361	Fuel and/or vehicle related fluids: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted.	Vehicle-related business: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted.	Not applicable: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted.	Clean-up: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted. , Other: waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted.	waste truck leaked hydraulic fluid to pavement. spill was cleaned up. no drains impacted.
WAR044503	7/9/2024	7/9/2024	Pollution hotline (phone, web, app): report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions.	Yes, Notified Ecology	3510 s holly st	Seattle	98118	47.542721	-122.288240	Sewage/septage/pet waste/human waste: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions.	Unconfirmed, unspecified, or not identified: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions.	Not applicable: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions.	Clean-up: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions. , Other: report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions.	report of sewage dumped to road and drain. investigated site- 1-2gal of sewage impacted catch basin; no outfall to ms4. workorder created to clean catch basin. no further actions.
WAR044503	8/5/2024	8/5/2024	MS4 inspection or screening: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed.	Yes, Notified Ecology	s holly st & 44th ave s	Seattle	98118	47.542465	-122.278117	Other: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed.	Unconfirmed, unspecified, or not identified: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed.	Not applicable: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed.	Other: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed. , Other: spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed.	Complaint. spu identified trigger level fluoride concentration in the ms4. source tracing sampling found the issue was not ongoing. area is residential and issue was most likely related to irrigation. no further investigation is needed.
WAR044503	12/9/2024	12/9/2024	Pollution hotline (phone, web, app): report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable.	Yes, Notified Ecology	458 n 44th st	Seattle	98103	47.660376	-122.352924	Unconfirmed, unspecified, or not identified: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable.	Unconfirmed, unspecified, or not identified: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable.	Not applicable: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable.	Clean-up: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable. , Other: report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable.	Complaint. report of possible sewage surfacing and flowing onto sidewalk. spu frc was dispatched to investigate. spu source control investigated and found inconclusive evidence at this time that this is a sewer leak but it is still probable.
WAR044503	12/27/2024	12/27/2024	ERTS referral: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place.	Yes, No Notice Required	5022 martin luther king jr way s	Seattle	0	0	0	Other: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place.	Construction activity: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place.	Not applicable: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place.	Other: report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place.	Complaint. report of a violation of a construction stormwater permit at an active construction site. site inspection found no continuing issues with stormwater bmps in place.
WAR044503	1/30/2024	1/30/2024	Pollution hotline (phone, web, app): spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill.	Yes, No Notice Required	1519 alaskan way s	Seattle	98134	47.590172	-122.338008	Fuel and/or vehicle related fluids: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill.	Other accident/spill: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill.	Not applicable: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill.	Education/technical assistance: spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill.	spu spills received call from coast guard of spill in their parking lots. no impact ms4. cg cleaned spill.
WAR044503	1/20/2024	1/20/2024	Pollution hotline (phone, web, app): gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4	Yes, No Notice Required	sw myrtle st / 23rd ave sw	Seattle	98106	47.539147	-122.361647	Fuel and/or vehicle related fluids: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4	Intentional dumping: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4	Not applicable: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4	Clean-up: gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4	gas tank of a pick up, parked on side of street, had been drilled with gas going to pavement. report came in to spills the next morning. found sheen on road and used granular to clean up. no drainage structures impacted and no impact to ms4
WAR044503	4/14/2024	4/14/2024	Pollution hotline (phone, web, app): bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb.	Yes, Notified Ecology	26th ave sw / sw roxbury st	Seattle	47.517362	-122.365923	47.517362	Fuel and/or vehicle related fluids: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb.	Vehicle-related business: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb.	Not applicable: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb.	Clean-up: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb. , Other: bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb.	bus leaked coolant to street and minor amount entered ms4 catch basin. bus company cleaned the street and cb.
WAR044503	5/20/2024	5/20/2024	Pollution hotline (phone, web, app): report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted.	Yes, Notified Ecology	2500 15th ave s	Seattle	98144	47.580818	-122.313086	Food-related oil/grease: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted.	Intentional dumping: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted.	Not applicable: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted.	Clean-up: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted. , Other: report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted.	Complaint. report of soapy water being discharged into cb. investigated and found cb filled with greasy water. hired contractor for cleaning. ms4 impacted.
WAR044503	8/14/2024	8/14/2024	Pollution hotline (phone, web, app): report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4.	Yes, No Notice Required	12815 aurora ave n	Seattle	98133	47.722966	-122.345478	Other: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4.	Other: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4.	Not applicable: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4.	Education/technical assistance: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4. , Other: report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4.	Complaint. report of vehicle washing and wash water entering into nearby cb. none found. no impact to ms4.
WAR044503	9/13/2024	9/13/2024	Pollution hotline (phone, web, app): spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party.	Yes, Notified Ecology	9200 roosevelt way ne	Seattle	0	0	0	Fuel and/or vehicle related fluids: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party.	Vehicle-related business: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party.	Not applicable: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party.	Clean-up: spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party.	spill of coolant from a bus. impact to right of way with no drainage involvement. clean up completed by responsible party.
WAR044503	6/23/2024	6/23/2024	Pollution hotline (phone, web, app): report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired.	Yes, Notified Ecology	2527 29th ave s	Seattle	0	0	0	Sewage/septage/pet waste/human waste: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired.	Unconfirmed, unspecified, or not identified: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired.	Not applicable: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired.	Clean-up: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired. , Other: report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired.	report of sewage leaking to pavement. investigated- private side sewer broken causing 100 gallons of sewage/solids to discharge to pavement and catch basin. cleanup of site completed. no outfall to drainage mainline or water body. side sewer repaired.
WAR044503	4/4/2024	4/4/2024	Pollution hotline (phone, web, app): sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. site manager hired plumber and vactor service to fix issue. side sewer restored.	Yes, Notified Ecology	1401 madison st	Seattle	98112	47.610650	-122.321262	Sewage/septage/pet waste/human waste: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4.	Other accident/spill: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4.	Not applicable: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4.	Education/technical assistance: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4. , Other: sso event. 1200 gallons of sewage made its way into lake union by way of the ms4.	sso event. 1200 gallons of sewage made its way into lake union by way of the ms4.
WAR044503	6/14/2024	6/14/2024	Direct report to your staff: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program.	Yes, No Notice Required	rainier ave s/s cloverdale st	Seattle	98118	47.526170	-122.269994	Sewage/septage/pet waste/human waste: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program.	Intentional dumping: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program.	Not applicable: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program.	Clean-up: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program. , Other: rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program.	rv leaking sewage into right of way. no drainage impacts. spill cleaned up by spu spill response. client referred to rv wastewater program.
WAR044503	1/2/2024	1/2/2024	Pollution hotline (phone, web, app): large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted.	Yes, No Notice Required	823 madison st	Seattle	98104	47.608150	-122.327457	Other: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted.	Other: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted.	Not applicable: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted.	Clean-up: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted. , Other: large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted.	large fire created heavy water flow into the ms4 drains in the area. drains were inspected for accumulation of fire debris. work orders to clean three cbs were submitted.
WAR044503	11/15/2024	11/15/2024	Pollution hotline (phone, web, app): spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue.	Yes, Notified Ecology	4009 stone way n	Seattle	0	0	0	Fuel and/or vehicle related fluids: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue.	Other accident/spill: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue.	Not applicable: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue.	Clean-up: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue. , Other: spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue.	spu spill response dispatched to report of hydraulic spill to roadway. assisted responsible/reporting party mitigate spill. no drains impacted. rp ertsd issue.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	11/7/2024	11/7/2024	Pollution hotline (phone, web, app): report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4.	Yes, Notified Ecology	8580 sandpoint way	Seattle	98115	0	0	Other: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4.	Vehicle-related business: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4.	Not applicable: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4.	Clean-up: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4. , Other: report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4.	Complaint. report of one pint of hydraulic fluid spilled from commercial vehicle due to a mechanical problem. none found. no impact to ms4.
WAR044503	10/30/2024	10/30/2024	ERTS referral: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4.	Yes, Notified Ecology	1300 e pine st	Seattle	98122	47.615536	-122.315170	Fuel and/or vehicle related fluids: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4.	Vehicle-related business: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4.	Not applicable: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4.	Clean-up: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4. , Other: report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4.	Complaint. report of 1/2 gallon of diesel spill due to mechanical problem on commercial vehicle. spiller cleaned up and disposed of waste. no impact to ms4.
WAR044503	1/22/2024	1/22/2024	Pollution hotline (phone, web, app): report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4.	Yes, No Notice Required	11759 4th ave nw	Seattle	98177	47.715904	-122.362530	Fuel and/or vehicle related fluids: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4.	Vehicle-related business: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4.	Not applicable: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4.	Clean-up: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4. , Other: report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4.	report of odor coming from a sheen in row. used pads to clean up approximately 1/4 gallon. no impact to ms4.
WAR044503	2/29/2024	2/29/2024	Pollution hotline (phone, web, app): report of leaking vehicle in row. investigated-- minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4.	Yes, Notified Ecology	7433 california ave sw	Seattle	98136	47.536070	-122.387773	Fuel and/or vehicle related fluids: report of leaking vehicle in row. investigated-- minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4.	Vehicle-related business: report of leaking vehicle in row. investigated-- minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4.	Not applicable: report of leaking vehicle in row. investigated-- minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4.	Other: report of leaking vehicle in row. investigated-- minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4.	report of leaking vehicle in row. investigated-- minimal sheen to curb line in row. non recoverable material, less than 1 cup. impact direct to drainage mainline/ ms4.
WAR044503	8/13/2024	8/13/2024	MS4 inspection or screening: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology.	Yes, Notified Ecology	s warsaw st & 39th ave s	Seattle	98118	47.543182	-122.283302	Other: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology.	Construction activity: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology.	Not applicable: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology.	Other: received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology.	Complaint. received trigger level results for fluoride. source tracing found a broken hydrant flowing into the ms4. repair work order is already made. notified ecology.
WAR044503	9/28/2024	9/28/2024	Pollution hotline (phone, web, app): vehicle accident spilled fluids to roadway. no drains impacted.	Yes, No Notice Required	16th ave ne / ne 50th st	Seattle	98108	47.664883	-122.310812	Fuel and/or vehicle related fluids: vehicle accident spilled fluids to roadway. no drains impacted.	Vehicle collision: vehicle accident spilled fluids to roadway. no drains impacted.	Not applicable: vehicle accident spilled fluids to roadway. no drains impacted.	Other: vehicle accident spilled fluids to roadway. no drains impacted.	vehicle accident spilled fluids to roadway. no drains impacted.
WAR044503	12/11/2024	12/11/2024	ERTS referral: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated.	Yes, Notified Ecology	3015 nw 54th st	Seattle	98107	47.667437	-122.396349	Fuel and/or vehicle related fluids: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated.	Other accident/spill: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated.	Not applicable: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill was mitigated.	Clean-up: spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated.	Complaint. spu spill response received erts from contractor detailing spill of hydraulic fluid and diesel. erts advised no drains impacted and spill mitigated by contractor. spu spills visited site and concurred with information contained in erts. no drains impacted and spill was mitigated.
WAR044503	4/23/2024	4/23/2024	ERTS referral: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4.	Yes, Notified Ecology	4700 denver ave s	Seattle	98108	47.560685	-122.332418	Other: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4.	Vehicle-related business: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4.	Not applicable: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4.	Clean-up: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4. , Other: report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4.	Complaint. report of commercial vehicle spilling five gallons of hydraulic fluid onto pavement. investigated and spiller cleaned up spilled material. no impact to ms4.
WAR044503	6/13/2024	6/13/2024	Pollution hotline (phone, web, app): report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4.	Yes, No Notice Required	4100 university way ne	Seattle	98105	47.656978	-122.312920	Food-related oil/grease: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4.	Intentional dumping: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4.	Not applicable: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4.	Clean-up: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4. , Other: report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4.	report of 55 gal drum of used cooking oil knocked over by vandals behind restaurant. placed absorbent granules down for safety and called mahoney/hauler for clean up. no impact to ms4.
WAR044503	5/11/2024	5/11/2024	Pollution hotline (phone, web, app): commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted.	Yes, No Notice Required	14th ave / e madison st	Seattle	98108	47.613894	-122.314231	Fuel and/or vehicle related fluids: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted.	Vehicle-related business: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted.	Not applicable: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted.	Clean-up: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted. , Other: commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted.	commercial vehicle spilled two gallons of hydraulic fluid on pavement and into cb due to mechanical failure. cleaned up by responsible party. ms4 impacted.
WAR044503	3/13/2024	3/13/2024	Pollution hotline (phone, web, app): received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage.	Yes, No Notice Required	s raymond st / 32nd ave s	Seattle	98108	47.547965	-122.291563	Sewage/septage/pet waste/human waste: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage.	Intentional dumping: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage.	Not applicable: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage.	Clean-up: received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage.	received a report of sewage being dumped over a manhole. site visit confirmed about 5-10 gallons of sewage was dumped over a drainage line lid. cleaned with on hand materials, and it appeared no sewage entered the ms4. notified ecology due to the proximity of the sewage.
WAR044503	3/27/2024	3/27/2024	Pollution hotline (phone, web, app): spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage.	Yes, No Notice Required	709 n 94th st	Seattle	98103	47.696126	-122.348845	Fuel and/or vehicle related fluids: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage.	Other accident/spill: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage.	Not applicable: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage.	Clean-up: spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage.	spu spills responded to report of motor oil and/or gas in alleyway. spu investigated report and found sheen of likely hydraulic fluid on pavement and in catch basin. hydrophobic pads were placed in d/s cb and universal pads were used to clean heavy sheen on pavement. nrc report 12-1224; erts submitted #729849. spill contained to site drainage.
WAR044503	6/11/2024	6/11/2024	Pollution hotline (phone, web, app): self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Yes, Notified Ecology	6225 37th ave ne	Seattle	98115	47.674722	-122.288296	Fuel and/or vehicle related fluids: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Vehicle-related business: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Not applicable: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	Clean-up: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact. , Other: self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.	self report of a coolant spill to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 drain impact.
WAR044503	2/21/2024	2/21/2024	Pollution hotline (phone, web, app): spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue.	Yes, No Notice Required	8715 aurora ave n	Seattle	98103	47.692440	-122.345187	Fuel and/or vehicle related fluids: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue.	Intentional dumping: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue.	Not applicable: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue.	Clean-up: spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue.	spu spill response dispatched to report of motor oil dumping to catch basin. spu found 1 gallon of motor oil in cb. cleaned with hydrophobic pads. investigated d/s stormwater mainline did not observe evidence of oil. ertsed issue.
WAR044503	7/3/2024	7/3/2024	MS4 inspection or screening: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined.	Yes, Notified Ecology	s sullivan st & 42nd ave s	Seattle	98118	47.526763	-122.280874	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined.	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined.	Not applicable: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined.	Other: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined. , Other: spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined.	Complaint. spu dry weather screening identified trigger level surfactant concentration in the ms4. follow up source tracing found the issue was not ongoing and a source was not able to be determined.
WAR044503	8/5/2024	8/5/2024	Direct report to your staff: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned.	Yes, Notified Ecology	1222 s weller st	Seattle	98144	47.597808	-122.316044	Food-related oil/grease: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned.	Other: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned.	Not applicable: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned.	Clean-up: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. , Education/technical assistance: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. , Education/technical assistance: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned. , Enforcement: during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned.	during a pollution prevention inspection used cooking oil was found in a drain. the company was issued a corrective action letter requiring this drain and parking lot surface be cleaned.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	11/5/2024	11/5/2024	Pollution hotline (phone, web, app): sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure.	Yes, Notified Ecology	12346 24th ave ne	Seattle	98125	47.719003	-122.303418	Sewage/septage/pet waste/human waste: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure.	Other: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure.	Not applicable: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure.	Education/technical assistance: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. . Referred to other agency or department: sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure. .	sewage coming out of spu mainline ended up in lake washington. ms4 impacted due to equipment failure of pump and bypass set up. equipment fixed and responsible party updated maintenance procedure.
WAR044503	11/4/2024	11/4/2024	ERTS referral: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted.	Yes, Notified Ecology	13201 aurora ave n	Seattle	98133	47.725456	-122.346604	Fuel and/or vehicle related fluids: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted.	Vehicle collision: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted.	Not applicable: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted.	Clean-up: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted., Other: commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted.	Complaint. commerial vehicle hit curb and ruptured fuel tank spilling approximately 15 gallons of diesel onto pavement and into private cb. contractor hired for cleanup. ms4 impacted.
WAR044503	3/25/2024	3/25/2024	Pollution hotline (phone, web, app): self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact.	Yes, Notified Ecology	1206 university st	Seattle	98101	47.612242	-122.325772	Fuel and/or vehicle related fluids: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact.	Vehicle-related business: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact.	Not applicable: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact.	Clean-up: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact., Other: self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact.	self reported spill of coolant to pavement from a leaking waste collection truck. cleanup completed by the responsible party. spu site visit found residual evidence of the cleanup effort with no ms4 impact.
WAR044503	2/29/2024	2/29/2024	Pollution hotline (phone, web, app): electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site.	Yes, Notified Ecology	s riverside dr / s holden st	Seattle		47.534135	-122.325435	Sewage/septage/pet waste/human waste: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site.	Construction activity: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site.	Not applicable: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site.	Referred to other agency or department: electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site. .	electrical issues caused pump station to stop, ultimately causing sanitary sewer system to surcharge and sewage flow from maintenance holes and into separated drainage. discharge went to duwamish river and cbo site.
WAR044503	10/12/2024	10/12/2024	Pollution hotline (phone, web, app): bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted.	Yes, Notified Ecology	sw spokane st / detridge way sw	Seattle	98106	47.572094	-122.360020	Fuel and/or vehicle related fluids: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted.	Vehicle-related business: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted.	Not applicable: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted.	Clean-up: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted., Other: bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted.	bus leaked coolant to roadway. responsible party cleaned up the roadway. no drains impacted.
WAR044503	3/20/2024	3/20/2024	Direct report to your staff: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program.	Yes, No Notice Required	military rd s & s othello st	Seattle	98108	47.536692	-122.296495	nfa_spills, Sewage/septage/pet waste/human waste: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program.	Intentional dumping: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program.	Not applicable: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program.	Referred to other agency or department: rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program.	Complaint. rv reported to have leaked sewage to pavement. no recoverable sewage detected. site referred to rv wastewater program.
WAR044503	8/6/2024	8/6/2024	Pollution hotline (phone, web, app): report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4.	Yes, No Notice Required	2910 w smith st	Seattle	98199	47.641409	-122.394798	Fuel and/or vehicle related fluids: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4.	Vehicle-related business: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4.	Not applicable: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4.	Clean-up: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4., Other: report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4.	report of oil spilled from garbage/recycling vehicle. cleaned up using absorbent granules. no impact to ms4.
WAR044503	4/9/2024	4/9/2024	Pollution hotline (phone, web, app): diesel spilled from dock. containment and absorbent boom applied. no impact to ms4.	Yes, No Notice Required	1801 16th ave sw	Seattle	98134	47.586026	-122.353148	Fuel and/or vehicle related fluids: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4.	Other accident/spill: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4.	Not applicable: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4.	Clean-up: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4., Other: diesel spilled from dock. containment and absorbent boom applied. no impact to ms4.	diesel spilled from dock. containment and absorbent boom applied. no impact to ms4.
WAR044503	12/3/2024	12/3/2024	ERTS referral: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa.	Yes, Notified Ecology	814 ne northlake pl	Seattle	98103	47.655033	-122.319035	Fuel and/or vehicle related fluids: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa.	Other accident/spill: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa.	Not applicable: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa.	Clean-up: hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa.	Complaint. hydraulic fluid spilled while cleaning up a diesel spill. all was contained and cleaned. no impact to ms4. nfa.
WAR044503	2/1/2024	2/1/2024	Business inspection: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system.	Yes, Notified Ecology	2010 15th ave w	Seattle	98119	47.637150	-122.375695	Fuel and/or vehicle related fluids: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system.	Other accident/spill: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system.	Not applicable: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system.	Clean-up: a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system. .	a catch basin was found to contain weather motor oil during routine business inspection. the company was required to clean their drainage system.
WAR044503	8/29/2024	8/29/2024	ERTS referral: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated.	Yes, Notified Ecology	5100 25th ave ne	Seattle	98105	47.666677	-122.300355	Fuel and/or vehicle related fluids: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated.	Other accident/spill: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated.	Not applicable: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated.	Other: reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated.	reported gasoline spill. investigated spill. ms4 not impacted. spiller attempted to clean up. gasoline evaporated.
WAR044503	1/31/2024	1/31/2024	ERTS referral: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted.	Yes, Notified Ecology	33rd ave s / s dearborn st	Seattle		47.595768	-122.290283	Fuel and/or vehicle related fluids: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted.	Other accident/spill: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted.	Not applicable: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted.	Clean-up: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted., Other: above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted.	above ground home heating oil leaked. homeowner hired contractor to cleanup. no drains impacted.
WAR044503	11/19/2024	11/19/2024	Pollution hotline (phone, web, app): report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4.	Yes, Notified Ecology	4115 sw admiral way	Seattle	98116	47.580959	-122.384827	Fuel and/or vehicle related fluids: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4.	Other accident/spill: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4.	Not applicable: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4.	Clean-up: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4., Other: report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4.	report of gasoline spill at a gas station. affected pavement was cleaned with absorbent pads and peat moss. no impact to ms4.
WAR044503	11/9/2024	11/9/2024	Pollution hotline (phone, web, app): approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted.	Yes, Notified Ecology	4705 ne 54th st	Seattle	98105	0	0	Sewage/septage/pet waste/human waste: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted.	Vehicle-related business: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted.	Not applicable: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted.	Clean-up: approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted. .	approximately 400 gallons of sewage spilled from vactor truck. 150 gallons was recovered and 250 discharged into union bay bogs land. ms4 impacted.
WAR044503	12/27/2024	12/27/2024	Pollution hotline (phone, web, app): spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line.	Yes, Notified Ecology	6th ave s & s holgate st	Seattle	98108	47.586173	-122.325985	Fuel and/or vehicle related fluids: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line.	Vehicle-related business: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line.	Not applicable: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line.	Referred to other agency or department: spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line. .	spill of motor oil to pavement and sanitary sewer. sdot completed cleanup on roadway. unrecoverable sheen in sanitary sewer line.
WAR044503	8/14/2024	8/14/2024	Pollution hotline (phone, web, app): spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet.	Yes, Notified Ecology	103 23rd ave	Seattle	98122	47.601815	-122.302731	Other: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet.	Other accident/spill: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet.	Not applicable: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet.	Clean-up: spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet. .	spu spill response received a report from a waste hauler that paint spill from a dumpster. when attempting to clean the spill, fugitive washwater with some paint reached a private drain. the waste hauler ertsed the issue and is cleaning the drain. no evidence the discolored washwater left the catch basin as water level was below the outlet.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	4/21/2024	4/21/2024	Pollution hotline (phone, web, app): got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it.	Yes, No Notice Required	1001 fairview ave n	Seattle	98109	47.629018	-122.331739	Fuel and/or vehicle related fluids: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it.	Unconfirmed, unspecified, or not identified: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it.	Not applicable: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it.	Referred to other agency or department: got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it.	got a spill report of sheen on south lake union from an unknown source. site visit confirmed the sheen, but found no source. no sheen was seen at the nearby spu outfall. I notified ecology of the incident and they were already aware of it.
WAR044503	3/19/2024	3/19/2024	ERTS referral: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains.	Yes, Notified Ecology	10013 m l king jr way s	Seattle	98178	47.511226	-122.279262	Fuel and/or vehicle related fluids: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains.	Vehicle collision: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains.	Not applicable: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains.	Clean-up: received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains.	Complaint. received a report of a diesel being spilled at a loading dock. site visit confirmed diesel entered a private separated drainage system, that flows to the ms4. there was no evidence of it reaching the ms4, it all stayed on private property. responsible party did the reporting and hired a contractor to clean the drains.
WAR044503	5/13/2024	5/13/2024	Pollution hotline (phone, web, app): rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater	Yes, No Notice Required	8850 9th ave sw	Seattle	98106	47.523193	-122.346471	Sewage/septage/pet waste/human waste: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater	Intentional dumping: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater	Not applicable: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater	Clean-up: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater. Education/technical assistance: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater. Referred to other agency or department: rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater	rv leaking black water to pavement. no drain impacts. cleaned by spill response and referral to rv wastewater
WAR044503	3/29/2024	3/29/2024	Pollution hotline (phone, web, app): report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered.	Yes, No Notice Required	9102 fauntleroy way sw	Seattle	98136	47.522442	-122.392438	Sediment/soil: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered.	Construction activity: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered.	Not applicable: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered.	Other: report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered.	report of cloudy water in fauntleroy creek. did not observe any. i did observe a construction company that did not have fabric filters in drains, sediment and rock all over roadway and soil piles not covered.
WAR044503	7/10/2024	7/10/2024	Pollution hotline (phone, web, app): received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste.	Yes, No Notice Required	520 s brandon st	Seattle	98108	47.555152	-122.327508	Fuel and/or vehicle related fluids: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste.	Vehicle-related business: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste.	Not applicable: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste.	Clean-up: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste. Other: received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste.	received a spill page about a coolant spill in a parking lot. site visit confirmed it was a spill of coolant to a private parking lot with no drain involvement. responsible party cleaned and disposed of the waste.
WAR044503	8/31/2024	8/31/2024	Pollution hotline (phone, web, app): report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4.	Yes, No Notice Required	2401 n northlake way	Seattle	98103	47.651036	-122.329963	Other: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4.	Unconfirmed, unspecified, or not identified: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4.	Not applicable: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4.	Referred to other agency or department: report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4.	report of sheen in waterway from unknown origin. referred to wa ecology via nrc. ecy called and said they will take this case. no impact to ms4.
WAR044503	4/7/2024	4/7/2024	Pollution hotline (phone, web, app): sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa.	Yes, Notified Ecology	2121 26th ave s	Seattle	98144	47.584114	-122.299112	Sewage/septage/pet waste/human waste: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa.	Other accident/spill: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa.	Not applicable: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa.	Clean-up: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. , Clean-up: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. , Referred to other agency or department: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa. , Other: sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa.	sewage reported from sso. plumber called to repair. 20 gal to ms4. nfa.
WAR044503	12/12/2024	12/12/2024	Pollution hotline (phone, web, app): report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact.	Yes, No Notice Required	1801 41st ave e	Seattle	98112	47.634722	-122.279875	Other: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact.	Other: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact.	Not applicable: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact.	Other: report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact.	report of liquids leaking from a garbage compactor into a drain. verified drain goes to combined sewer and scheduled business inspection. no ms4 impact.
WAR044503	7/17/2024	7/17/2024	Pollution hotline (phone, web, app): construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted.	Yes, Notified Ecology	1810 7th ave w	Seattle	98119	47.635144	-122.365946	Other: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted.	Other: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted.	Not applicable: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted.	Clean-up: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. , Enforcement: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted. , Other: construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted.	construction company cut concrete and allow the slurry to spill onto pavement and enter into a cb. company instructed to clean pavement and cb. ms4 impacted.
WAR044503	10/28/2024	10/28/2024	Pollution hotline (phone, web, app): drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4.	Yes, No Notice Required	12028 32nd ave ne	Seattle	98125	0	0	Fuel and/or vehicle related fluids: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4.	Intentional dumping: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4.	Not applicable: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4.	Referred to other agency or department: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4. , Other: drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4.	drilled fuel tank spilled an unknown amount to pavement. sdot cleaned up. no impact to ms4.
WAR044503	3/12/2024	3/12/2024	Pollution hotline (phone, web, app): report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs.	Yes, No Notice Required	9211 7th ave nw	Seattle	98117	47.696546	-122.365029	Fuel and/or vehicle related fluids: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs.	Vehicle-related business: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs.	Not applicable: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs.	Clean-up: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs. nfa_spills. Education/technical assistance: report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs.	report of oil leaking from a pickup truck on the right of way. small oil spill cleaned up by spu with no drainage impacts. responsible party advised of the leak and instructed to contain and cleanup any spill oil while they affect repairs.
WAR044503	5/3/2024	5/3/2024	Pollution hotline (phone, web, app): spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required.	Yes, Notified Ecology	12600 stone ave n	Seattle	98133	47.721334	-122.341026	Fuel and/or vehicle related fluids: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required.	Other accident/spill: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required.	Not applicable: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required.	Clean-up: spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required.	spill of diesel fuel at haller lake fuel station. impact to oil water separator, no fuel passed the chamber. fuel cleaned up by spu spill response. notice to orc to have structure inspected for futher cleaning if required.
WAR044503	3/25/2024	3/25/2024	Pollution hotline (phone, web, app): report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact.	Yes, Notified Ecology	1531 14th ave	Seattle	98122	47.615102	-122.314624	Sewage/septage/pet waste/human waste: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact.	Other accident/spill: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact.	Not applicable: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact.	Clean-up: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact. , Other: report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact.	report of a sewer overflow in the row. spu responded and determined the cause was a private side sewer problem. the responsible party hired a contractor to resolve the issue and spu implemented bmps and a beach closure due to the ms4 impact.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments	
WAR044503	9/21/2024	9/21/2024	Pollution hotline (phone, web, app): report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup.	Yes, No Notice Required	9640 16th ave sw	burien	0	0	0	nfa_spills	Food-related oil/grease: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup.	Unconfirmed, unspecified, or not identified: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup.	Not applicable: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup.	Referred to other agency or department: report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup.	report of cooking oil spill. outside of Seattle jurisdiction. referred to state for followup.
WAR044503	4/10/2024	4/10/2024	Direct report to your staff: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4.	Yes, No Notice Required	213 nw 56th st	Seattle	98107	47.699729	-122.359969	Other: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4.	Other: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4.	Not applicable: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4.	Education/technical assistance: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4. , Other: report of turbid water being discharged off property. none found upon my arrival. no impact to ms4.	Complaint. report of turbid water being discharged off property. none found upon my arrival. no impact to ms4.	
WAR044503	6/3/2024	6/3/2024	Pollution hotline (phone, web, app): vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted.	Yes, No Notice Required	41st ave sw & 100th st	Seattle	98136	47.513765	-122.384604	Fuel and/or vehicle related fluids: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted.	Vehicle collision: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted.	Not applicable: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted.	Other: vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted.	vehicle accident left sheen in street. no recoverable product. impacted vegetated ditch and culvert but did not travel far. no recovery attempted.	
WAR044503	7/25/2024	7/25/2024	ERTS referral: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4.	Yes, Notified Ecology	8011 faunterroy way sw	Seattle	98136	47.531160	-122.393211	Fuel and/or vehicle related fluids: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4.	Vehicle-related business: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4.	Not applicable: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4.	Clean-up: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. , Education/technical assistance: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4. , Other: report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4.	Complaint. report of leaking vehicle parked over cb. motor oil has leaked onto pavement, none in cb. cleaned with on hand materials. no impact to ms4.	
WAR044503	11/4/2024	11/4/2024	Pollution hotline (phone, web, app): found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa.	Yes, Notified Ecology	n 87th st & greenwood ave n	Seattle	98103	47.692437	-122.355317	Fuel and/or vehicle related fluids: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa.	Unconfirmed, unspecified, or not identified: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa.	Not applicable: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa.	Clean-up: found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa.	found odor of gasoline with sheen in puddle. no impact to downstream catch basin. odor strongest in leaf pile. swept up leaves. no recoverable product on puddle. nfa.	
WAR044503	9/13/2024	9/13/2024	ERTS referral: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4.	Yes, Notified Ecology	6733 east marginal way s	Seattle	98108	47.541872	-122.327148	Fuel and/or vehicle related fluids: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4.	Intentional dumping: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4.	Not applicable: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4.	Clean-up: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. , Clean-up: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4. , Other: gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4.	gasoline spilled due to gas tank getting drilled at a business. some gasoline entered private catch basin. contractor hired by business cleaned out the structure. no evidence found the gas has left cb and made it to the ms4.	
WAR044503	2/28/2024	2/28/2024	Pollution hotline (phone, web, app): report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted.	Yes, Notified Ecology	s brandon st / 50th ave s	Seattle	47.553360	-122.270915	Unconfirmed, unspecified, or not identified: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted.	Unconfirmed, unspecified, or not identified: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted.	Not applicable: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted.	Other: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted. , Other: report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted.	report of sheen on street coming from construction. investigated-- substance is not oil, but coming from city construction operating equipment. bmps inserted at site. no visual observation of ms4 impacted.		
WAR044503	5/27/2024	5/27/2024	Pollution hotline (phone, web, app): commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted.	Yes, Notified Ecology	36th ave ne / ne 45th st	Seattle	98105	47.661149	-122.289231	Fuel and/or vehicle related fluids: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted.	Vehicle-related business: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted.	Not applicable: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted.	Clean-up: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted. , Other: commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted.	commerial vehicle spilled 25 gallons of coolant which impact storm drain and pavement. responsible party cleaned up spilled material. ms4 impacted.	
WAR044503	10/8/2024	10/8/2024	Pollution hotline (phone, web, app): vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa.	Yes, Notified Ecology	57th ave sw / sw admiral way	Seattle	0	0	0	Sediment/soil: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa.	Other accident/spill: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa.	Not applicable: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa.	Clean-up: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. , Clean-up: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa. , Other: vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa.	vactor accidentally spilled 1/2 a yard of sediment. spill was cleaned up after minimal wash water entered ms4. no downstream involvement. nfa.	
WAR044503	6/20/2024	6/20/2024	Pollution hotline (phone, web, app): received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology.	Yes, Notified Ecology	2040 westlake ave n	Seattle	98109	47.637336	-122.339890	Fuel and/or vehicle related fluids: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology.	Intentional dumping: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology.	Not applicable: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology.	Clean-up: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology. , Other: received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology.	received a spill report about a punctured gas tank leaking gas into the storm drain. site visit confirmed gas had entered the ms4. the gas was confined to the cb and did not make it the waterbody. we put boom in the drain for a few days until the drain was clean. i notified ecology.	
WAR044503	4/4/2024	4/4/2024	ERTS referral: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa	Yes, Notified Ecology	n 90th st & stone ave n	Seattle	98103	47.694169	-122.341891	Fuel and/or vehicle related fluids: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa	Other accident/spill: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa	Not applicable: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa	Clean-up: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa. , Referred to other agency or department: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa. , Other: fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa.	fuel sheen found on pavement. referred to sdot for street sweeper. sheen did not make it into inlet. ms4 impacted. nfa	
WAR044503	12/20/2024	12/20/2024	Pollution hotline (phone, web, app): cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations.	Yes, No Notice Required	1050 sw spokane st	Seattle	98134	47.571928	-122.347301	Fuel and/or vehicle related fluids: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations.	Other accident/spill: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations.	Not applicable: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations.	Clean-up: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations. , Referred to other agency or department: cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations.	cargo crane leaked hydraulic oil to wharf and dock. spiller cleaned up the oil on the deck but not in the dock. port of Seattle supervised cleanup of their tenant operations.	
WAR044503	6/12/2024	6/12/2024	ERTS referral: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4.	Yes, Notified Ecology	905 ne 114th st	Seattle	98125	47.711369	-122.319051	Fuel and/or vehicle related fluids: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4.	Vehicle-related business: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4.	Not applicable: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4.	Other: commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4.	Complaint. commerial vehicle had a mechanical failure and spilled one gallon of hydraulic fluid onto street. cleaned up by responsible party. no impact to ms4.	
WAR044503	9/16/2024	9/16/2024	MS4 inspection or screening: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Yes, Notified Ecology	s pearl st & 39th ave s	Seattle	98118	47.556207	-122.283487	Other: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Not applicable: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Other: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary. , Other: spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Complaint. spu dry weather screening found trigger level results for fluoride in the ms4. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	
WAR044503	9/30/2024	9/30/2024	Pollution hotline (phone, web, app): report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek.	Yes, No Notice Required	20th ave ne / ne 91st st	Seattle	98115	47.694846	-122.306828	Sediment/soil: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek.	Other: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek.	Not applicable: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek.	Clean-up: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek. , Other: report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek.	report of turbidity in the creek. found a likely source of turbidity from spu ditch and culvert cleaning operations at 20th ave ne / ne 91st st. advised the crews to improve bmps to keep sediment out of the creek.	

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	6/5/2024	6/5/2024	Pollution hotline (phone, web, app): fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall.	Yes, Notified Ecology	7242 seawave ave nw	Seattle	98117	47.682135	-122.403613	Fuel and/or vehicle related fluids: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall.	Vehicle-related business: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. Other accident/spill: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall.	Not applicable: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall.	Clean-up: fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall. fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall.	fuel line to an rv generator leaked gasoline to the street, curb line, inlet, drainage line, and into puget sound. the leak was stopped and absorbents applied to prevent further impact to drainage and local waters. the site was monitored to ensure bmps were adequate to prevent sheen at the outfall. no further sheen was visible at the outfall.
WAR044503	12/6/2024	12/6/2024	Pollution hotline (phone, web, app): commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted.	Yes, Notified Ecology	poplar pl s / s dearborn st	Seattle		47.595813	-122.312831	Fuel and/or vehicle related fluids: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted.	Vehicle-related business: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted.	Not applicable: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted.	Other: commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted.	commercial vehicle leaked coolant to the roadway. spiller cleaned up the spill and no drains were impacted.
WAR044503	2/6/2024	2/6/2024	Pollution hotline (phone, web, app): self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup.	Yes, No Notice Required	401 alaskan way s	Seattle	98104	47.597018	-122.336580	Other: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup.	Construction activity: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup.	Not applicable: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup.	Clean-up: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup. Other: self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup.	self reported spill of construction spoils from a port of Seattle construction site impacting pavement and a port owned separated storm drainage system. port of Seattle reported to ecology and coordinated cleanup.
WAR044503	5/14/2024	5/14/2024	Direct report to your staff: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4.	Yes, No Notice Required	1100 w ewing st	Seattle	98119	47.656922	-122.370603	Fuel and/or vehicle related fluids: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4.	Other: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4.	Not applicable: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4.	Other: marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4.	Complaint. marine vessel moored pier side sunk for an unknown reason. several hundred gallons of oil released into the waterway. federal agencies and contractor cleaning up. no impact to ms4.
WAR044503	7/25/2024	7/25/2024	Pollution hotline (phone, web, app): report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4.	Yes, No Notice Required	5209 shilshoe ave nw	Seattle	98107	47.664262	-122.383409	Other: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4.	Unconfirmed, unspecified, or not identified: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4.	Not applicable: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4.	Referred to other agency or department: report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4.	report of large sheen in shilshoe marina from uscg. referred to ecy. no impact to ms4.
WAR044503	5/19/2024	5/19/2024	Pollution hotline (phone, web, app): hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4.	Yes, Notified Ecology	7 s idaho st	Seattle	98134	47.564499	-122.341983	Fuel and/or vehicle related fluids: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4.	Vehicle-related business: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4.	Not applicable: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4.	Clean-up: hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4.	hydraulic fluid spilled to pavement from a garbage truck. company performed cleanup. no impact to drainage/ms4.
WAR044503	5/14/2024	5/14/2024	Pollution hotline (phone, web, app): report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted.	Yes, Notified Ecology	47th ave sw / sw webster st	Seattle		47.535802	-122.392588	Fuel and/or vehicle related fluids: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. , Fuel and/or vehicle related fluids: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. , Food-related oil/grease: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted.	Intentional dumping: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted.	Not applicable: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted.	Clean-up: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted. , Other: report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted.	report of motor oil dumped in cb. investigation found motor oil, anti freeze and cooking oil in cb. hired graymar to clean. ms4 impacted.
WAR044503	6/4/2024	6/4/2024	Pollution hotline (phone, web, app): report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water.	Yes, No Notice Required	2858 13th ave w	Seattle	98119	47.646557	-122.373327	Other: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water.	Unconfirmed, unspecified, or not identified: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water.	Not applicable: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water.	Other: report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water.	Complaint. report of sewage surfacing. investigation found no issues with the spu infrastructure. material tested negative for sewage and appears to be ground water.
WAR044503	5/3/2024	5/3/2024	Pollution hotline (phone, web, app): commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Yes, No Notice Required	611 20th ave s	Seattle	98144	47.597259	-122.306616	Fuel and/or vehicle related fluids: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Vehicle-related business: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Not applicable: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Clean-up: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4. , Other: commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	commerial truck spilled one gallon of hydraulic fluid due to mechanical failure. responsible party cleaned up spilled material. no impact to ms4.
WAR044503	3/29/2024	3/29/2024	Pollution hotline (phone, web, app): report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted.	Yes, Notified Ecology	500 s portland st	Seattle	98108	47.533640	-122.326701	Other: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted.	Other accident/spill: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted.	Not applicable: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted.	Clean-up: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted. , Other: report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted.	report of two gallons of coolant spilled onto the pavement and into cb. contractor hired to cleanup spill. ms4 impacted.
WAR044503	9/12/2024	9/12/2024	MS4 inspection or screening: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Yes, Notified Ecology	35th ave s / s alaska st	Seattle		47.560752	-122.288832	Other: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Not applicable: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Other: spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.	Complaint. spu dry weather screening found trigger level results for conductivity in the ms4. source tracing concluded the issue to be not ongoing, no further source tracing is necessary.
WAR044503	11/11/2024	11/11/2024	Pollution hotline (phone, web, app): received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary.	Yes, No Notice Required	4115 sw admiral way	Seattle	98116	47.580959	-122.384827	Other: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary.	Other accident/spill: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary.	Not applicable: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary.	Clean-up: received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary.	Complaint. received a spill report about a small gasoline spill at a gas station with no drain involvement. responsible party hired contractors to clean the pavement. site visit confirmed the spill had been cleaned properly. no further investigation is necessary.
WAR044503	1/10/2024	1/10/2024	Pollution hotline (phone, web, app): diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4.	Yes, Notified Ecology	2325 harbor ave sw	Seattle	98126	47.582353	-122.374136	Fuel and/or vehicle related fluids: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4.	Other accident/spill: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4.	Not applicable: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4.	Clean-up: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4. , Other: diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4.	diesel spilled from commercial vehicle due to gas cap not being in place. pavement and two cbs were impacted. responsible party hired contractor. no impact to ms4.
WAR044503	3/20/2024	3/20/2024	Pollution hotline (phone, web, app): self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Yes, Notified Ecology	8748 25th pl ne	Seattle	98115	47.693381	-122.300622	Fuel and/or vehicle related fluids: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Vehicle-related business: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Not applicable: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Clean-up: self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact.	self reported spill of hydraulic fluid to pavement from a waste collection truck. cleanup completed by the responsible party. no ms4 impact.
WAR044503	8/23/2024	8/23/2024	Pollution hotline (phone, web, app): spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed.	Yes, No Notice Required	1808 believee ave	Seattle		0	0	Food-related oil/grease: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed.	Unconfirmed, unspecified, or not identified: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed.	Not applicable: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed.	Other: spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed.	spu spill response dispatched to report of grease spill in row. minimal evidence of spill at site. no clean-up performed. ds cb and inlet and curblines showed no evidence of oil/grease. no erts filed.
WAR044503	10/16/2024	10/16/2024	Pollution hotline (phone, web, app): report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap.	Yes, Notified Ecology	8512 nesbit aven n	Seattle	98103	47.691033	-122.343188	Fuel and/or vehicle related fluids: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap.	Intentional dumping: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap.	Not applicable: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap.	Clean-up: report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap.	Complaint. report of automotive work in right of way and oil dumping to catch basin. investigation found no active car work or responsible party. impacted catch basin cleaned of oil by spu spills. oil contained to single basin due to outlet trap.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/15/2024	2/15/2024	ERTS referral: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4.	Yes, Notified Ecology	1300 n 97th st	Seattle	98103	47.699779	-122.341618	Other: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4.	Other accident/spill: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4.	Not applicable: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4.	Clean-up: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4. . Other: two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4.	Complaint. two gallons of diesel onto pavement and spiller cleaned it up. no impact to ms4.
WAR044503	12/19/2024	12/19/2024	Pollution hotline (phone, web, app): report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4.	Yes, No Notice Required	3207 point pl sw	Seattle	98116	0	0	Sewage/septage/pet waste/human waste: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4.	Other accident/spill: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4.	Not applicable: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4.	Clean-up: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4. . Other: report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4.	report of sewage exiting floor drain and inlet on private property. property owner hired plumber. no impact to ms4.
WAR044503	11/5/2024	11/5/2024	Pollution hotline (phone, web, app): sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property.	Yes, Notified Ecology	4200 37th ave s	Seattle	98118	47.565338	-122.285808	Unconfirmed, unspecified, or not identified: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. . Other: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property.	Illicit connection: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property.	Not applicable: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property.	Education/technical assistance: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. . Referred to other agency or department: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property. . Other: sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property.	sewage found pumped from house ms4. illicit connection stopped and beach closure implemented. further investigation needed to resolve possible flooding of property.
WAR044503	11/8/2024	11/8/2024	Direct report to your staff: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4.	Yes, No Notice Required	8830 lake city way ne	Seattle	98115	47.692882	-122.305179	Soap or cleaning chemicals: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4.	Other: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4.	Not applicable: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4.	Education/technical assistance: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4. . Other: i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4.	Complaint. i witnessed an auto dealership using soap to wash vehicles. soap impacted soil and pavement. i had them stop the washing. no impact to ms4.
WAR044503	7/22/2024	7/22/2024	MS4 inspection or screening: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing.	Yes, Notified Ecology	42nd ave s & s thistle st	Seattle	98136	47.527864	-122.280872	Other: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing.	Unconfirmed, unspecified, or not identified: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing.	Not applicable: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing.	Other: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing. . Other: spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing.	Complaint. spu dry weather screening received a potassium trigger in the ms4. further sampling concluded the issue is not ongoing.
WAR044503	9/10/2024	9/10/2024	ERTS referral: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4.	Yes, Notified Ecology	4501 27th ave ne	Seattle	98105	47.661412	-122.298009	Other: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4.	Vehicle-related business: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4.	Not applicable: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4.	Clean-up: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4. . Other: report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4.	Complaint. report of commercial vehicle spilling one gallon of hydraulic fluid to pavement due to mechanical failure. none found. no impact to ms4.
WAR044503	9/26/2024	9/26/2024	Pollution hotline (phone, web, app): unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected.	Yes, Notified Ecology	3902 s ferdinand st	Seattle	98118	47.558067	-122.283202	Fuel and/or vehicle related fluids: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected.	Unconfirmed, unspecified, or not identified: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected.	Not applicable: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected.	Clean-up: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected. . Other: unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected.	unknown spill of gasoline that impacted ms4 catch basin. spills cleaned gasoline out with absorbent pads and had spu crews clean structures affected.
WAR044503	4/6/2024	4/6/2024	Pollution hotline (phone, web, app): sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa	Yes, Notified Ecology	9540 4th ave nw	Seattle	98117	47.699126	-122.361744	Sediment/soil: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa	Construction activity: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa	Not applicable: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa	Clean-up: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa. Education/technical assistance: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa. Other: sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa	sediment run off from construction site. contractor asked to sweep curb line and clean the cb. ms4 impacted but cleaned with no evidence of soil downstream. nfa
WAR044503	8/16/2024	8/16/2024	Pollution hotline (phone, web, app): approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall.	Yes, Notified Ecology	1737 belmont ave	Seattle	98122	47.617439	-122.324830	Firefighting foam: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall.	Other: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall.	Not applicable: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall.	Other: approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall.	approximately three gallons of novacool used to extinguish building fire. ms4 impacted but did not see anything existing outfall.
WAR044503	9/9/2024	9/9/2024	Pollution hotline (phone, web, app): spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff. nfa_spills	Yes, No Notice Required	2225 alaskan way	Seattle	0	0	nfa_spills	Food-related oil/grease: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff.	Other accident/spill: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff.	Not applicable: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff.	Clean-up: spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff.	spill to pier on port of Seattle facility. no water or drain impacts. cleanup completed by port staff.
WAR044503	6/11/2024	6/11/2024	Staff referral: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted.	Yes, Notified Ecology	14th ave nw / nw 50th st	Seattle	98107	47.664751	-122.373106	Fuel and/or vehicle related fluids: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted.	Intentional dumping: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted.	Not applicable: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted.	Clean-up: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted. . Other: cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted.	cleaned up spill of approx 5oz of spilled motor oil in curb line. ms4 impacted. no drains or water bodies impacted.
WAR044503	8/17/2024	8/17/2024	Direct report to your staff: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted.	Yes, No Notice Required	19901 cedar falls rd se	north bend	98045	47.425844	-121.775793	Fuel and/or vehicle related fluids: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted.	Other accident/spill: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted.	Not applicable: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted.	Clean-up: spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted.	Complaint. spu spill response received e-mail report from watershed inspector that hydraulic spill had impacted road near cedar falls educational facility. spill was mitigated by watershed team. no impact to drains or ms4. no erts submitted.
WAR044503	8/19/2024	8/19/2024	Pollution hotline (phone, web, app): spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed.	Yes, No Notice Required	2727 fairview ave e	Seattle	98102	47.644948	-122.328181	Sediment/soil: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed.	Construction activity: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed.	Not applicable: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed.	Other: spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed.	spu spill response dispatched to a report of turbid water in lake union. issue was broken fire service line with that carried turbid water to inlet/catchbasin that flowed to lake union. incident was ertsed.
WAR044503	9/14/2024	9/14/2024	Pollution hotline (phone, web, app): report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel.	Yes, No Notice Required	2611 fairview ave e	Seattle	98102	47.645946	-122.327678	Unconfirmed, unspecified, or not identified: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel.	Unconfirmed, unspecified, or not identified: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel.	Not applicable: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel.	Referred to other agency or department: report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel.	report of a barrel floating in south lake union near a marina. contents of the barrel were unknown and it was not reported to be leaking. spu referred this to department of ecology to respond to. ecology was not able to locate the barrel.
WAR044503	6/18/2024	6/18/2024	Pollution hotline (phone, web, app): commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4.	Yes, No Notice Required	3rd ave s / s walker st	Seattle	98134	47.583901	-122.329486	Fuel and/or vehicle related fluids: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4.	Vehicle-related business: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4.	Not applicable: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4.	Clean-up: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4. . Other: commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4.	commercial vehicle spilled an undetermined amount of hydraulic fluid onto several roads. contractor hired for cleanup. no impact to ms4.
WAR044503	9/3/2024	9/3/2024	Direct report to your staff: motor vehicle accident impacted an rv and released black and grey wastewater to pavement.	Yes, No Notice Required	4523 5th ave ne	Seattle	0	0	0	Sewage/septage/pet waste/human waste: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. . Sewage/septage/pet waste/human waste: motor vehicle accident impacted an rv and released black and grey wastewater to pavement.	Vehicle collision: motor vehicle accident impacted an rv and released black and grey wastewater to pavement.	Not applicable: motor vehicle accident impacted an rv and released black and grey wastewater to pavement.	Referred to other agency or department: motor vehicle accident impacted an rv and released black and grey wastewater to pavement. . Other: motor vehicle accident impacted an rv and released black and grey wastewater to pavement.	motor vehicle accident impacted an rv and released black and grey wastewater to pavement.
WAR044503	2/28/2024	2/28/2024	Pollution hotline (phone, web, app): approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4.	Yes, Notified Ecology	6847 54th ave ne	Seattle	98115	47.678966	-122.270604	Fuel and/or vehicle related fluids: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4.	Vehicle-related business: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4.	Not applicable: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4.	Clean-up: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4. . Other: approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4.	approximately one cup of petroleum from an unknown source causing an oil sheen in the street against the curbline. i cleaned the sheen using spill pads. no impact to ms4.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	1/2/2024	1/2/2024	Pollution hotline (phone, web, app): contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thorton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid.	Yes, Notified Ecology	11033 27th ave ne	Seattle	98125	47.709543	-122.289442	Sediment/soil: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thorton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid.	Other: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thorton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid.	Not applicable: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thorton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid.	Clean-up: contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thorton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid.	contractor was pumping out turbid water from a temporary trench and into separated drainage system that then entered a creek (tributary to south branch of thorton). contractor was asked to clean out 3 impacted spu drainage structures. contractor had vactor truck complete cleanup the following day. creek was checked again and was no longer turbid.
WAR044503	1/20/2024	1/20/2024	Pollution hotline (phone, web, app): small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up.	Yes, No Notice Required	2502 sw findlay st	Seattle	98106	47.552103	-122.364697	Sewage/septage/pet waste/human waste: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up.	Other accident/spill: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up.	Not applicable: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up.	Clean-up: small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up.	small overflow of sewage from a pump chamber on a private side sewer serving 3 apartments. sewage had not left the property and no drains were impacted. requested owner contact plumber to resolve issue. referred to side sewer program for follow up.
WAR044503	6/20/2024	6/20/2024	ERTS referral: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued.	Yes, Notified Ecology	3717 beach dr sw	Seattle	98116	47.570538	-122.411786	Sewage/septage/pet waste/human waste: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued.	Other accident/spill: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued.	Not applicable: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued.	Enforcement: we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued.	Complaint. we received a spill report about sewage leaking from underneath a condo, the sewage direct discharges to the puget sound. this is a known problem area with history. the side sewer was repaired and an nov was issued.
WAR044503	5/9/2024	5/9/2024	Pollution hotline (phone, web, app): concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted.	Yes, Notified Ecology	3313 s oregon st	Seattle	98118	47.562669	-122.290262	Other: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted.	Other accident/spill: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted.	Not applicable: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted.	Clean-up: concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted.	concrete truck spilled about two gallons of concrete into row and about half gallon entered into cb. spiller cleaned up concrete from row and cb. ms4 impacted.
WAR044503	9/9/2024	9/9/2024	MS4 inspection or screening: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary.	Yes, Notified Ecology	s royal brougham way / 4th ave s	Seattle	98134	47.592393	-122.329059	Other: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary.	Unconfirmed, unspecified, or not identified: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary.	Not applicable: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary.	Other: spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary.	Complaint. spu received trigger level results for surfactants in the ms4. source tracing concluded it was not an ongoing issue. no further investigation is necessary.
WAR044503	2/20/2024	2/20/2024	Pollution hotline (phone, web, app): report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted.	Yes, Notified Ecology	7413 faunterroy way sw	Seattle	98136	47.536607	-122.392519	Food-related oil/grease: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted.	Intentional dumping: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted.	Not applicable: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted.	Clean-up: report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted.	Complaint. report of cooking oil dumped into cb. arrived at location and there is approximately four gallons in a cb causing a clog. responsible party will clean cb and jet line. ms4 impacted.
WAR044503	10/3/2024	10/3/2024	ERTS referral: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted.	Yes, Notified Ecology	5th ave s / s spokane st	Seattle		47.571419	-122.327472	Other: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted.	Vehicle-related business: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted.	Not applicable: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted.	Clean-up: report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted.	Complaint. report of one quart of engine coolant spilled from a commercial vehicle. responsible party hired contractor for cleanup. ms4 impacted.
WAR044503	10/24/2024	10/24/2024	Pollution hotline (phone, web, app): commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Yes, Notified Ecology	11606 3rd ave ne	Seattle	98125	0	0	Fuel and/or vehicle related fluids: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Vehicle-related business: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Not applicable: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Clean-up: commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	commercial vehicle spilled 1/2 gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.
WAR044503	2/11/2024	2/11/2024	Pollution hotline (phone, web, app): received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact.	Yes, No Notice Required	portage bay	Seattle		47.647925	-122.313170	Fuel and/or vehicle related fluids: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact.	Unconfirmed, unspecified, or not identified: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact.	Not applicable: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact.	Other: received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact.	received a report of sheen in portage bay. site visit confirmed old sheen with no odor in various spots. no source was found, no ms4 impact.
WAR044503	1/16/2024	1/16/2024	Pollution hotline (phone, web, app): hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted.	Yes, Notified Ecology	4500 west marginal way sw	Seattle	98106	47.563193	-122.350679	Fuel and/or vehicle related fluids: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted.	Vehicle-related business: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted.	Not applicable: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted.	Clean-up: hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted.	hydraulic hose ruptured on commercial vehicle spilling 25 gallons of fluid onto pavement and into a cb. contractor hired for cleanup. ms4 impacted.
WAR044503	2/5/2024	2/5/2024	Pollution hotline (phone, web, app): report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact.	Yes, No Notice Required	4115 sw admiral way	Seattle	98116	47.580959	-122.384827	Fuel and/or vehicle related fluids: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact.	Intentional dumping: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact.	Not applicable: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact.	Clean-up: report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact.	report of a gasoline spill to pavement at a fuel station due to a vandalized private vehicle. cleanup completed by the fuel station. no ms4 impact.
WAR044503	10/9/2024	10/9/2024	Direct report to your staff: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4.	Yes, No Notice Required	5512 22nd ave nw	Seattle	98107	47.669257	-122.384350	Other: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4.	Other accident/spill: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4.	Not applicable: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4.	Other: report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4.	Complaint. report of private cb clogged with leaves and sediment. this is responsibility of property owner. no impact to ms4.
WAR044503	2/21/2024	2/21/2024	Pollution hotline (phone, web, app): spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up.	Yes, No Notice Required	4058 rainier ave s	Seattle	98118	47.567014	-122.288201	Fuel and/or vehicle related fluids: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up.	Other accident/spill: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up.	Not applicable: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up.	Clean-up: spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up.	spu spills received report of one gallon diesel spill at local business. no drains impacted. business ertsed issue. business provided before and after pictures of spill clean up.
WAR044503	12/10/2024	12/10/2024	Direct report to your staff: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed.	Yes, No Notice Required	6332 38th ave sw	Seattle	98126	47.545530	-122.377475	Fuel and/or vehicle related fluids: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed.	Unconfirmed, unspecified, or not identified: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed.	Not applicable: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed.	Clean-up: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed.	Complaint. a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. reporting party sent back an email with photos and videos but none could be opened. sediment saturated in gasoline was found in an inlet that flows to the curbline. d/s cb was not impacted. sediment was removed.
WAR044503	1/17/2024	1/17/2024	Pollution hotline (phone, web, app): oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted.	Yes, Notified Ecology	8601 aurora ave n	Seattle	98103	47.691607	-122.345006	Fuel and/or vehicle related fluids: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted.	Intentional dumping: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted.	Not applicable: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted.	Clean-up: oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted.	oil spilled from vandalized vehicle spilling into row and on cb. used oil pad to clean cb. ms4 impacted.
WAR044503	8/5/2024	8/5/2024	MS4 inspection or screening: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing.	Yes, Notified Ecology	s garden st & 48th ave s	Seattle	98118	47.537635	-122.272645	Other: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing.	Unconfirmed, unspecified, or not identified: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing.	Not applicable: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing.	Clean-up: spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing.	Complaint. spu dry weather screening identified elevated fecal results in the ms4. source tracing sampling and cctv investigation of the drainage mainline was not able to confirm a source. the source tracing investigation is ongoing.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	8/11/2024	8/11/2024	Pollution hotline (phone, web, app): solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa.	Yes, Notified Ecology	aurora ave n / n 93rd st	Seattle	98103	47.696349	-122.344613	Other: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa.	Vehicle collision: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa., Other accident/spill: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa.	Not applicable: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa.	Clean-up: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa., Clean-up: solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa.	solvent reported, found decking stain in two junction boxes. crews deployed to remove product. ms4 impacted but was contained to two structures. nfa.
WAR044503	3/10/2024	3/10/2024	Pollution hotline (phone, web, app): caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain.	Yes, Notified Ecology	11th ave / e olive st	Seattle		47.616421	-122.318189	Fuel and/or vehicle related fluids: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain.	Unconfirmed, unspecified, or not identified: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain.	Not applicable: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain.	Other: caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain.	caller saw sheen on a pathway. sheen was from unknown source. as a precaution, a mesh absorbent pillow was placed in the nearby drain.
WAR044503	1/4/2024	1/4/2024	Staff referral: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa.	Yes, Notified Ecology	11th ave nw / nw ballard way	Seattle	98107	47.662927	-122.370778	Fuel and/or vehicle related fluids: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa.	Intentional dumping: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa.	Not applicable: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa.	Clean-up: planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa.	Complaint. planned rv relocation. inspected 13 catch basins and found one with unrecoverable sheen. sweeper dispatched for street and pads in cb. ms4 impacted. nfa.
WAR044503	6/7/2024	6/7/2024	Pollution hotline (phone, web, app): reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact.	Yes, Notified Ecology	10344 fischer pl ne	Seattle	98125	47.704241	-122.299189	Other: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact.	Unconfirmed, unspecified, or not identified: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact.	Not applicable: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact.	Referred to other agency or department: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact., Other: reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact.	reported concern of woody debris dumping to a creek. spu site visit confirmed the debris but was unable to determine a source or rule out natural deposition. no ms4 impact.
WAR044503	9/3/2024	9/3/2024	Pollution hotline (phone, web, app): report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted.	Yes, No Notice Required	6727 mlk jr way s	Seattle	98118	0	0	Food-related oil/grease: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted.	Intentional dumping: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted.	Not applicable: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted.	Clean-up: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted., Other: report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted.	report of five gallons of used cooking oil dumped in cb. spu crew will clean cb. ms4 impacted.
WAR044503	1/6/2024	1/6/2024	Pollution hotline (phone, web, app): received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program.	Yes, No Notice Required	3256 nw 54th st	Seattle	98107	47.667980	-122.400688	Other: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program.	Other accident/spill: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program.	Not applicable: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program.	Referred to other agency or department: received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program.	Complaint. received a report of a possible side sewer issue. when on site there was no active discharge, and the system was functioning as designed. the site has history, refer to inspection 163520, the reporting party was concerned that the pump system set in place is not a permanent fix. i referred the site the side sewer program.
WAR044503	11/21/2024	11/21/2024	Pollution hotline (phone, web, app): self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Yes, Notified Ecology	14320 36th ave ne	Seattle		0	0	Fuel and/or vehicle related fluids: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Other accident/spill: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Not applicable: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	Clean-up: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact., Referred to other agency or department: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact., Other: self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.	self report from Seattle city light of an oil spill to pavement and soil from a downed power transformer. cleanup coordinated by city light. no ms4 drain impact.
WAR044503	12/23/2024	12/23/2024	Pollution hotline (phone, web, app): report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci.	Yes, No Notice Required	1500 broadway	Seattle	98122	47.614359	-122.320288	Other: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci.	Other: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci.	Not applicable: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci.	Referred to other agency or department: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci., Other: report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci.	Complaint. report of gas station removing tanks and leaving debris everywhere. no impact to ms4. referred to sdci.
WAR044503	9/6/2024	9/6/2024	Pollution hotline (phone, web, app): responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented.	Yes, Notified Ecology	n 34th st & stone way n	Seattle	98103	47.648525	-122.342788	Sewage/septage/pet waste/human waste: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented.	Construction activity: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented.	Not applicable: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented.	Referred to other agency or department: responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented.	responded to a dry weather sewer overflow. 350 gallons of sewage stayed within the sanitary sewer line and overflowed through a cso outfall into lake union. the beach closure procedure was implemented.
WAR044503	5/19/2024	5/19/2024	Pollution hotline (phone, web, app): small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4.	Yes, Notified Ecology	e howell st & 15th ave	Seattle	98122	47.617618	-122.312778	Fuel and/or vehicle related fluids: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4.	Intentional dumping: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4.	Not applicable: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4.	Clean-up: small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4.	small spill of used motor oil to sidewalk, planting strip and curb. spu cleaned up with absorbent and pads. no impact to ms4.
WAR044503	1/21/2024	1/21/2024	Pollution hotline (phone, web, app): sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product.	Yes, No Notice Required	5609 26th ave sw	Seattle	98106	47.551611	-122.366008	Fuel and/or vehicle related fluids: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product.	Intentional dumping: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product.	Not applicable: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product.	Clean-up: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product., Other: sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product.	sheen seen in front of two properties that have a portion of longfellow creek running through their front yards. reporting party said issue had been going off and on for a week. put boom into the creek. source of sheen believed to be from a tube of an oil based beauty product.
WAR044503	11/1/2024	11/1/2024	Pollution hotline (phone, web, app): reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa.	Yes, Notified Ecology	2700 w commodore way	Seattle	98199	47.663043	-122.391705	Fuel and/or vehicle related fluids: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa.	Other accident/spill: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa.	Not applicable: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa.	Clean-up: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa., Referred to other agency or department: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa., Other: reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa.	reporting party dispatched clean up crew for coolant spill and called regulators. direct discharger, no impact to ms4. nfa.
WAR044503	11/1/2024	11/1/2024	ERTS referral: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa.	Yes, Notified Ecology	6718 21st ave sw	Seattle	98106	47.542175	-122.359287	Other: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa.	Construction activity: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa.	Not applicable: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa.	Education/technical assistance: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa., Other: asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa.	asphalt laid for roadway plate stabilization letting off gray sheen. no impact to ms4. nfa.
WAR044503	7/15/2024	7/15/2024	Pollution hotline (phone, web, app): commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4.	Yes, Notified Ecology	520 terry ave	Seattle	98104	47.606003	-122.323170	Fuel and/or vehicle related fluids: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4.	Vehicle-related business: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4.	Not applicable: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4.	Clean-up: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4., Other: commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4.	commercial vehicle had a hydraulic hose malfunction causing ten gallons of hydraulic fluid to spill onto the pavement and into a cb. responsible party hired contractor for cleanup. no impact to ms4.
WAR044503	9/18/2024	9/18/2024	Pollution hotline (phone, web, app): spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant.	Yes, Notified Ecology	8316 35th ave sw	Seattle	98126	47.528536	-122.376284	Fuel and/or vehicle related fluids: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant.	Other accident/spill: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant.	Not applicable: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant.	Clean-up: spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant.	spu spills dispatched to report of motor oil spill near drains. no drains impacted but ertsd as motor oil was spilled. cleaned with on hand granular absorbant.
WAR044503	12/6/2024	12/6/2024	ERTS referral: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor.	Yes, Notified Ecology	7739 1st ave s	Seattle	98106	47.533655	-122.337336	Fuel and/or vehicle related fluids: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor.	Vehicle-related business: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor.	Not applicable: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor.	Other: spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor.	spill of vehicle fluids in commercial property. no drains impacted. responsible party cleaned up the spill using spill contractor.
WAR044503	1/22/2024	1/22/2024	Pollution hotline (phone, web, app): leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted.	Yes, No Notice Required	9718 rainier ave s	Seattle	98118	47.516262	-122.254023	Fuel and/or vehicle related fluids: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted.	Vehicle-related business: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted.	Not applicable: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted.	Clean-up: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted., Education/technical assistance: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted., Other: leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted.	leaking crane caused oil to enter onto pavement, cb and lake wa. ms4 impacted.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	12/10/2024	12/10/2024	Direct report to your staff: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4.	Yes, No Notice Required	13751 lake city way	Seattle	98125	47.729859	-122.292790	Other: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4.	Other accident/spill: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4.	Not applicable: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4.	Other: a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4.	Complaint. a report of a gasoline spill was made to the illegal dumping group. the message was lost for a month and then spu spills was notified by email. no gasoline was found in the ms4.
WAR044503	2/6/2024	2/6/2024	ERTS referral: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4.	Yes, Notified Ecology	1009 e union st	Seattle	98122	47.612694	-122.318925	Other: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4.	Vehicle-related business: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4.	Not applicable: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4.	Other: report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4.	Complaint. report of commercial vehicle spilling an unknown amount of hydraulic fluid onto pavement and vehicle. none found. no impact to ms4.
WAR044503	6/12/2024	6/12/2024	Pollution hotline (phone, web, app): report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris.	Yes, No Notice Required	palm ave sw & sw atlantic st	Seattle	98116	47.590363	-122.284618	Fuel and/or vehicle related fluids: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris. Fuel and/or vehicle related fluids: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris.	Vehicle collision: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris.	Not applicable: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris.	Referred to other agency or department: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris. Other: report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris.	report from spd of an auto fluid spill due to a collision. spu investigated and determined no ms4 drain impact. internal referral to sdcf to complete row cleanup of fluid and debris.
WAR044503	4/1/2024	4/1/2024	Pollution hotline (phone, web, app): multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted.	Yes, No Notice Required	1001 fairview ave n	Seattle	98109	47.629018	-122.331739	Other: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted.	Other accident/spill: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted.	Not applicable: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted.	Other: multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted.	multiple calls for sheen in lake union from sinking boat. referred to ecology. spu spill responders checked multiple outfalls on multiple occasions. no sheen from outfalls. no erts submitted.
WAR044503	7/9/2024	7/9/2024	Pollution hotline (phone, web, app): unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4.	Yes, No Notice Required	e garfield st / fairview ave e	Seattle		47.633858	-122.326934	Sewage/septage/pet waste/human waste: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4.	Vehicle-related business: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4.	Not applicable: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4.	Clean-up: unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4.	unoccupied rv leaked .5 gallons of sewage onto pavement. cleaned up by wastewater rv contractor. no impact to ms4.
WAR044503	3/14/2024	3/14/2024	Pollution hotline (phone, web, app): report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4.	Yes, No Notice Required	3820 rainier ave s	Seattle	98118	47.569611	-122.288821	Fuel and/or vehicle related fluids: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4.	Intentional dumping: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4.	Not applicable: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4.	Clean-up: report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4.	report of two gallons of gasoline spilled from a drilled fuel tank. responsible company hired contractor to clean up. no impact to ms4.
WAR044503	4/24/2024	4/24/2024	Staff referral: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa.	Yes, No Notice Required	25th ave s / college st	Seattle		47.582933	-122.300353	Solid waste/trash: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa. Other: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa.	Intentional dumping: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa.	Not applicable: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa.	Clean-up: planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa.	Complaint. planned rv remediation. inspected 6 structures and found no sign of pollution. no impact to ms4. nfa.
WAR044503	3/30/2024	3/30/2024	Pollution hotline (phone, web, app): spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed.	Yes, No Notice Required	4401 4th ave s	Seattle	98134	47.565299	-122.330772	Fuel and/or vehicle related fluids: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed.	Vehicle collision: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed.	Not applicable: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed.	Referred to other agency or department: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed. Other: spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed.	spu spill response dispatched to report of mva with fluids going to a drain. visited accident site and no drains impacted. no erts filed.
WAR044503	7/29/2024	7/29/2024	Pollution hotline (phone, web, app): report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg.	Yes, Notified Ecology	2811 fairview ave e	Seattle	98102	47.645946	-122.327678	Fuel and/or vehicle related fluids: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg.	Unconfirmed, unspecified, or not identified: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg.	Not applicable: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg.	Other: report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg.	report of an unknown sheen on lake union. spu site visit confirmed the sheen and found no evidence the source was from the ms4. referred to ecology and uscg.
WAR044503	6/10/2024	6/10/2024	Pollution hotline (phone, web, app): report of pool contractor discharging water into row and it entered a drain. none found.	Yes, No Notice Required	212 32nd ave s	Seattle	98144	47.600428	-122.291066	Other: report of pool contractor discharging water into row and it entered a drain. none found.	Unconfirmed, unspecified, or not identified: report of pool contractor discharging water into row and it entered a drain. none found.	Not applicable: report of pool contractor discharging water into row and it entered a drain. none found.	Education/technical assistance: report of pool contractor discharging water into row and it entered a drain. none found. Other: report of pool contractor discharging water into row and it entered a drain. none found.	Complaint. report of pool contractor discharging water into row and it entered a drain. none found.
WAR044503	9/16/2024	9/16/2024	MS4 inspection or screening: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined.	Yes, Notified Ecology	s lucite st & 35th ave s	Seattle	98118	47.552497	-122.289330	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined.	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined.	Not applicable: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined.	Other: spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined.	Complaint. spu dry weather screening identified trigger level potassium concentration results in the ms4. upstream source tracing sampling found the issue is not ongoing. a source was not able to be determined.
WAR044503	9/10/2024	9/10/2024	MS4 inspection or screening: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Yes, Notified Ecology	s angeline st & 38th ave s	Seattle	98118	47.559460	-122.284942	Other: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Unconfirmed, unspecified, or not identified: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Not applicable: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Other: spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.	Complaint. spu dry weather screening found trigger level results for ammonia. source tracing concluded the issue to be not ongoing. no further source tracing is necessary.
WAR044503	3/29/2024	3/29/2024	Business inspection: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed.	Yes, No Notice Required	10711 aurora ave n	Seattle	98133	47.707086	-122.345321	Fuel and/or vehicle related fluids: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed.	Other accident/spill: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed.	Not applicable: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed.	Clean-up: during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed.	during a business inspection, sheen was found in a few spots throughout the property. the company was asked to clean the impacted areas. no drain impact, just surface sheen. the corrective actions were addressed and completed.
WAR044503	2/1/2024	2/1/2024	Pollution hotline (phone, web, app): report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement.	Yes, Notified Ecology	201 lake washington blvd	Seattle	98122	47.603136	-122.284965	Sediment/soil: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement.	Construction activity: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. Other: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement.	Not applicable: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement.	Education/technical assistance: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement. Other: report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement.	report of debris impact to a storm drain which was determined to be a landslide on private property. spu observed evidence of sediment impact to the row and an ms4 drain. internal referral to sdcf for bmp enforcement.
WAR044503	12/4/2024	12/4/2024	Pollution hotline (phone, web, app): sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer.	Yes, Notified Ecology	417 e union st	Seattle	98122	47.612817	-122.325919	Sewage/septage/pet waste/human waste: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer.	Other accident/spill: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer.	Not applicable: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer.	Clean-up: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer. Other: sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer.	sewer overflow from private side sewer serving an apartment building. sewage went to street and catch basin - ms4. crews pumped out catch basin. beach closure signs posted. plumber hired to repair side sewer.
WAR044503	6/4/2024	6/4/2024	Pollution hotline (phone, web, app): leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop.	Yes, No Notice Required	1300 n 97th st	Seattle	98103	47.699779	-122.341618	Fuel and/or vehicle related fluids: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop.	Vehicle-related business: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop.	Not applicable: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop.	Other: leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop.	leaking equipment in the equipment yard caused minor sheen to pavement. spu supplied oil pads to keep it out of the drain. equipment was sent in to the repair shop.
WAR044503	6/4/2024	6/4/2024	Pollution hotline (phone, web, app): garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains.	Yes, Notified Ecology	1515 believev ave	Seattle	98122	47.614528	-122.327199	Solid waste/trash: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains.	Other: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains.	Not applicable: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains.	Clean-up: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains. Other: garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains.	garbage truck fire due to improper battery disposal. garbage was dumped to street and fire extinguished by sfd. garbage was reloaded into the truck and the street swept and cleaned. only water from fire fighting entered drains.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/1/2024	2/1/2024	Pollution hotline (phone, web, app): report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined.	Yes, Notified Ecology	s forest st / rainier ave s	Seattle		47.577529	-122.297723	Fuel and/or vehicle related fluids: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined.	Vehicle-related business: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined., Intentional dumping: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined.	Not applicable: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined.	Clean-up: report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined.	report of motor oil impact to a storm drain due to auto work in the row. spu confirmed the sheen and used on hand absorbents to clean the affected row and ms4 drain. no responsible party was able to be determined.
WAR044503	12/8/2024	12/8/2024	Pollution hotline (phone, web, app): a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel.	Yes, Notified Ecology	49th ave s / s hudson st	Seattle		47.557068	-122.271937	Fuel and/or vehicle related fluids: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel.	Intentional dumping: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel.	Not applicable: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel.	Clean-up: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel., Education/technical assistance: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel., Other: a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel.	a vehicle was vandalized to steal fuel by drilling the fuel tank. fuel entered a ms4 catch basin but was contained in the structure. the cb was cleaned to remove the fuel. the street was cleaned to remove recoverable fuel.
WAR044503	2/10/2024	2/10/2024	Pollution hotline (phone, web, app): received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair.	Yes, Notified Ecology	3717 beach dr sw	Seattle	98116	47.570538	-122.411786	Sewage/septage/pet waste/human waste: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair.	Other accident/spill: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair.	Not applicable: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair.	Clean-up: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair., Education/technical assistance: received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair.	received a report of a leaking side sewer discharging to the sound. site visit confirmed a small leak, leaking directly into the sound. notified ecology, kcp, and washington state shellfish. signs were placed near the leak. responsible party hired a contractor to make the repair.
WAR044503	5/16/2024	5/16/2024	Pollution hotline (phone, web, app): investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4.	Yes, Notified Ecology	510 31st ave s	Seattle	98144	47.597628	-122.292438	Fuel and/or vehicle related fluids: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4.	Vehicle-related business: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4.	Not applicable: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4.	Clean-up: investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4.	investigated report of leaking vehicle. approx. 1 gal of fuel on pavement. cleaned up by responder using materials on hand. no impact to ms4.
WAR044503	7/23/2024	7/23/2024	Pollution hotline (phone, web, app): report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made.	Yes, No Notice Required	115 broadway e	Seattle	98102	47.619412	-122.321281	Other: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made.	Other: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made.	Not applicable: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made.	Other: report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made.	report of sewage crossing the sidewalk. this is washwater from parking lot cleaning. no soap used and possibly conditionally allowed discharge. a business inspection will be made.
WAR044503	4/6/2024	4/6/2024	Pollution hotline (phone, web, app): oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa.	Yes, Notified Ecology	renton ave s / 53rd ave s	Seattle		47.514812	-122.266530	Fuel and/or vehicle related fluids: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa.	Vehicle-related business: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa., Other accident/spill: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa., Intentional dumping: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa.	Not applicable: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa.	Clean-up: oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa.	oil reported. oil found and cleaned up. curb line ms4 impacted. no drains impacted. nfa.
WAR044503	8/22/2024	8/22/2024	Pollution hotline (phone, web, app): spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed.	Yes, Notified Ecology	7 s idaho st	Seattle	98134	47.564499	-122.341983	Fuel and/or vehicle related fluids: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed.	Other accident/spill: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed.	Not applicable: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed.	Clean-up: spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed.	spu spill response received call from local waste hauler about 2 quart hydraulic spill in yard. no drains impacted. no erts filed.
WAR044503	9/4/2024	9/4/2024	Pollution hotline (phone, web, app): report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4.	Yes, Notified Ecology	portage bay	Seattle		47.647925	-122.313170	Fuel and/or vehicle related fluids: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4.	Other: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4.	Not applicable: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4.	Referred to other agency or department: report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4.	report of sheen in portage bay. possibly related to sunken vessel from yesterday. no impact to ms4.
WAR044503	8/28/2024	8/28/2024	ERTS referral: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4.	Yes, Notified Ecology	s bangor st & renton ave s	Seattle	98178	0	0	Other: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4.	Vehicle-related business: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4.	Not applicable: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4.	Clean-up: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4., Other: report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4.	Complaint. report of commercial vehicle spilling three gallons of coolant onto pavement. none found. no impact to ms4.
WAR044503	1/2/2024	1/2/2024	Pollution hotline (phone, web, app): container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4.	Yes, No Notice Required	erskine way sw / lewis pt sw	Seattle		47.558836	-122.387551	Food-related oil/grease: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4.	Other accident/spill: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4.	Not applicable: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4.	Clean-up: container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4.	container of cooking oil spilled onto pavement and street. spill responder cleaned up and disposed of waste in trash can. no impact to ms4.
WAR044503	9/10/2024	9/10/2024	Pollution hotline (phone, web, app): restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4.	Yes, No Notice Required	9447 rainier ave s	Seattle	98118	47.519929	-122.263149	Soap or cleaning chemicals: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4.	Other: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4.	Not applicable: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4.	Education/technical assistance: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4., Other: restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4.	restaurant worker using soapy water to wash kitchen equipment in parking lot. made worker stop and educated him on code. no impact to ms4.
WAR044503	6/27/2024	6/27/2024	ERTS referral: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4.	Yes, Notified Ecology	7277 perimeter rd s	Seattle	98108	47.536852	-122.303928	Firefighting foam: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4.	Other accident/spill: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4.	Not applicable: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4.	Clean-up: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4., Referred to other agency or department: aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4.	Complaint. aff accidentally spilled and responsible party hired contractor to clean up. no foam made it into any drains. pictures show appropriate clean up. no impact to ms4.
WAR044503	2/1/2024	2/1/2024	Pollution hotline (phone, web, app): report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup.	Yes, Notified Ecology	14033 32nd ave ne	Seattle	98125	47.731078	-122.294228	Fuel and/or vehicle related fluids: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup.	Unconfirmed, unspecified, or not identified: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup.	Not applicable: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup.	Clean-up: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup., Education/technical assistance: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup., Education/technical assistance: report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup.	report of hydraulic fluid spill to pavement and private storm drains from an unknown source. spu site visit found the spill is motor oil and observed no ms4 or downstream impact. the responsible property manager completed cleanup.
WAR044503	9/30/2024	9/30/2024	MS4 inspection or screening: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary.	Yes, Notified Ecology	e pike st & 35th ave	Seattle	98122	47.614045	-122.288196	Other: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary.	Unconfirmed, unspecified, or not identified: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary.	Not applicable: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary.	Other: dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary.	Complaint. dry weather screening found trigger level results for fluoride in the city ms4. source tracing concluded that the issue is not ongoing. no further investigation is necessary.
WAR044503	7/4/2024	7/4/2024	Pollution hotline (phone, web, app): spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts.	Yes, No Notice Required	10215 greenwood ave n	Seattle	98133	47.703139	-122.356047	Fuel and/or vehicle related fluids: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts.	Intentional dumping: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts.	Not applicable: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts.	Other: spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts.	spill of gasoline to pavement at a private apartment complex. spu assisted the property manager with cleanup and waste disposal. no drain impacts.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	7/26/2024	7/26/2024	Pollution hotline (phone, web, app): spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses.	Yes, No Notice Required	3950 leary way nw	Seattle	98107	47.655098	-122.360591	Fuel and/or vehicle related fluids: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses.	Intentional dumping: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses.	Not applicable: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses.	nfa_spills, Education/technical assistance: spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses.	Complaint, spill of gasoline to pavement due to vandalism of a fuel tank during a fuel theft. no drain impacts. cleaned up by responsible party. technical assistance provided to impacted businesses.
WAR044503	3/6/2024	3/6/2024	Pollution hotline (phone, web, app): sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact.	Yes, Notified Ecology	3031 ne 137th st	Seattle	98125	47.727406	-122.294779	Sewage/septage/pet waste/human waste: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact.	Other accident/spill: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact.	Not applicable: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact.	Clean-up: sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact.	sewage discharge, approximately 13,500 gallons, to creek from private drainage infrastructure due to private side sewer blockage. contractor cleared the side sewer and used vactor to clear the sewer line. discharge from private drainage goes directly to creek; no ms4 impact.
WAR044503	5/28/2024	5/28/2024	Pollution hotline (phone, web, app): commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Yes, No Notice Required	sw avalon way / sw spokane st	Seattle		47.571366	-122.370636	Other: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Vehicle-related business: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Not applicable: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	Clean-up: commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4.	commercial vehicle spilled 24 quarts of coolant spilled due to a mechanical failure. responsible party cleaned up spilled material. no impact to ms4.
WAR044503	1/22/2024	1/22/2024	Pollution hotline (phone, web, app): fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement.	Yes, Notified Ecology	68th ave s / holyoke way s	Seattle		47.508632	-122.247962	Fuel and/or vehicle related fluids: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts.	Intentional dumping: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts.	Not applicable: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts.	Clean-up: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. Referred to other agency or department: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts. Other: fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts.	fuel tank on vehicle drilled spilling approximately three gallons of fuel onto pavement and gravel parking area. cleaned up and referred to parking enforcement. submitted erts.
WAR044503	7/3/2024	7/3/2024	Staff referral: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa.	Yes, Notified Ecology	21st ave s / s plum st	Seattle	98144	47.585499	-122.305577	Sewage/septage/pet waste/human waste: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa.	Intentional dumping: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa.	Not applicable: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa.	Clean-up: planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa.	Complaint, planned rv remediation. inspected 10 structures and found sewage in 2 cbs. ms4 impacted. nfa.
WAR044503	2/15/2024	2/15/2024	ERTS referral: report of an unknown amount of rusty water that entered into the bay. no impact to ms4.	Yes, Notified Ecology	1801 18th ave sw	Seattle	98134	47.586026	-122.353148	Other: report of an unknown amount of rusty water that entered into the bay. no impact to ms4.	Other accident/spill: report of an unknown amount of rusty water that entered into the bay. no impact to ms4.	Not applicable: report of an unknown amount of rusty water that entered into the bay. no impact to ms4.	Other: report of an unknown amount of rusty water that entered into the bay. no impact to ms4.	Complaint, report of an unknown amount of rusty water that entered into the bay. no impact to ms4.
WAR044503	11/5/2024	11/5/2024	Pollution hotline (phone, web, app): spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found.	Yes, Notified Ecology	water body	Seattle		47.650468	-122.356126	Fuel and/or vehicle related fluids: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found.	Unconfirmed, unspecified, or not identified: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found.	Not applicable: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found.	Referred to other agency or department: spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found.	spu spill response received report of sheen in fremont canal. sought dept of ecology's assistance. they advised that sheen had predominately dissipated, no source was located or concerns found.
WAR044503	3/21/2024	3/21/2024	Pollution hotline (phone, web, app): self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact.	Yes, No Notice Required	19th ave e / boyer ave e	Seattle		47.637922	-122.307288	Fuel and/or vehicle related fluids: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact.	Vehicle-related business: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact.	Not applicable: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact.	Clean-up: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact. Referred to other agency or department: self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact.	self reported spill of hydraulic fluid to pavement. cleanup completed by the responsible party. no ms4 impact.
WAR044503	12/16/2024	12/16/2024	Pollution hotline (phone, web, app): report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact.	Yes, No Notice Required	2525 14th ave s	Seattle	98144	47.580234	-122.315178	Fuel and/or vehicle related fluids: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact.	Unconfirmed, unspecified, or not identified: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact.	Not applicable: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact.	Clean-up: report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact.	report of sheen near a drain in a parking lot. observed traces of sheen near the reported private catch basin and cleaned absorbant pads. no sheen or product was found inside the catch basin, no ms4 impact.
WAR044503	8/22/2024	8/22/2024	Pollution hotline (phone, web, app): spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue.	Yes, Notified Ecology	2320 43rd ave e	Seattle	98112	47.639927	-122.276373	Sewage/septage/pet waste/human waste: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue.	Other accident/spill: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue.	Not applicable: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue.	Clean-up: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue. Referred to other agency or department: spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue.	spu spill response dispatched to report of a broken side sewer on a building that is over lake washington. water usage was minimized in the building, the side sewer repair undertaken. dept. of ecology and Seattle king county public health were made aware of the issue.
WAR044503	3/13/2024	3/13/2024	Pollution hotline (phone, web, app): two car accident. no impact to drainage.	Yes, No Notice Required	aurora ave n / n 140th st	Seattle		47.730490	-122.345067	Fuel and/or vehicle related fluids: two car accident. no impact to drainage.	Vehicle collision: two car accident. no impact to drainage.	Not applicable: two car accident. no impact to drainage.	Other: two car accident. no impact to drainage.	two car accident. no impact to drainage.
WAR044503	8/27/2024	8/27/2024	MS4 inspection or screening: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary.	Yes, Notified Ecology	s dakota st & 37th ave s	Seattle	98118	47.566167	-122.286105	Other: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary.	Unconfirmed, unspecified, or not identified: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary.	Not applicable: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary.	Other: spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary.	Complaint, spu dry weather screening received fluoride trigger levels in the ms4. source tracing found this not to be an ongoing issue. no further investigation is necessary.
WAR044503	12/13/2024	12/13/2024	Pollution hotline (phone, web, app): spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area	Yes, Notified Ecology	4700 denver ave s	Seattle	98108	47.560685	-122.332418	Fuel and/or vehicle related fluids: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area	Vehicle-related business: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area	Not applicable: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area	Clean-up: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area. Education/technical assistance: spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area.	spill of hydraulic oil on private property to a private drainage system. spiller hired a contractor to clean impacted areas. no impact to ms4 or receiving water or public property. department of ecology spill response inspected the spill area

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	1/3/2024	1/3/2024	Pollution hotline (phone, web, app): received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact.	Yes, Notified Ecology	2001 w garfield st	Seattle	98119	47.630999	-122.382825	Fuel and/or vehicle related fluids: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact.	Vehicle-related business: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact.	Not applicable: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact.	Clean-up: received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact.	received a report of a hydraulic spill due to a mechanical issue. responsible party applied absorbent and cleaned the spill properly. no ms4 impact.
WAR044503	4/3/2024	4/3/2024	Pollution hotline (phone, web, app): cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa.	Yes, Notified Ecology	14032 aurora ave n	Seattle	98133	47.731434	-122.344610	Other wastewater: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa., Soap or cleaning chemicals: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa.	Intentional dumping: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa.	Not applicable: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa.	Clean-up: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa., Education/technical assistance: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa., Other: cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa.	cleaning solution found in drains. contractor cleaned solution. ms4 impacted but mitigated by cleaning efforts. nfa.
WAR044503	4/12/2024	4/12/2024	Pollution hotline (phone, web, app): commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4.	Yes, Notified Ecology	4100 mosevelt way ne	Seattle	98105	47.657086	-122.317499	Sewage/septage/pet waste/human waste: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4.	Other accident/spill: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4.	Not applicable: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4.	Clean-up: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4., Education/technical assistance: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4., Other: commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4.	commercial building with blocked side sewer. business hired a plumber to relieve the blockage. erts was filed due to minor impact to ms4. frc managed overflow at the cb to prevent flow of sewage down the ms4.
WAR044503	8/16/2024	8/16/2024	Pollution hotline (phone, web, app): spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health.	Yes, No Notice Required	beacon ave s/s graham st	Seattle		0	0	Fuel and/or vehicle related fluids: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health.	Vehicle collision: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health.	Not applicable: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health.	Clean-up: spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health.	spu spill response dispatched to mva. one gallon of gas to curblin. no drains impacted. no erts filed given volume and minimal risk to property and health.
WAR044503	8/15/2024	8/15/2024	Pollution hotline (phone, web, app): spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted.	Yes, No Notice Required	8724 mary ave nw	Seattle	98117	47.693222	-122.374970	Fuel and/or vehicle related fluids: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted.	Intentional dumping: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted.	Not applicable: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted.	Clean-up: spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted.	spu spills responded to a drilled gas tank; approximately 10 gallons of gas was released to the curblin. spu spills mitigated spill and referred to sdot for further assessment. erts submitted given volume of gasoline. no drains impacted.
WAR044503	9/27/2024	9/27/2024	ERTS referral: caller reported spill to parking lot. photos were provided to verify that no drains were impacted.	Yes, Notified Ecology	3407 airport way s	Seattle	98134	47.573503	-122.322398	Fuel and/or vehicle related fluids: caller reported spill to parking lot. photos were provided to verify that no drains were impacted.	Vehicle-related business: caller reported spill to parking lot. photos were provided to verify that no drains were impacted.	Not applicable: caller reported spill to parking lot. photos were provided to verify that no drains were impacted.	Clean-up: caller reported spill to parking lot. photos were provided to verify that no drains were impacted., Education/technical assistance: caller reported spill to parking lot. photos were provided to verify that no drains were impacted., Other: caller reported spill to parking lot. photos were provided to verify that no drains were impacted.	caller reported spill to parking lot. photos were provided to verify that no drains were impacted.
WAR044503	7/22/2024	7/22/2024	Pollution hotline (phone, web, app): report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested.	Yes, No Notice Required	water body	Seattle		47.636837	-122.333631	Fuel and/or vehicle related fluids: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested.	Unconfirmed, unspecified, or not identified: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested.	Not applicable: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested.	Referred to other agency or department: report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested.	report of sheen on lake union. referred to ecology as lead agency and offered assistance if requested.
WAR044503	6/26/2024	6/26/2024	Pollution hotline (phone, web, app): drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa.	Yes, Notified Ecology	9622 25th ave ne	Seattle	98115	47.699156	-122.301317	Other: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa., Other: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa.	Vehicle-related business: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa.	Not applicable: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa.	Clean-up: drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa.	drips amounting to a pint was spilled from a trash truck into the driver stopped the vehicle and arrested the leak. the drips were cleaned with peat moss. spill did not make it to the conveyance system and was contained to the right of way. nfa.
WAR044503	10/30/2024	10/30/2024	Pollution hotline (phone, web, app): car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction.	Yes, Notified Ecology	i5 northbound / south of west Seattle bridge	Seattle		47.570667	-122.320117	Unconfirmed, unspecified, or not identified: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction.	Vehicle collision: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction.	Not applicable: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction.	Referred to other agency or department: car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction.	car fire on n i5 exit towards columbia way going east. no impact to ms4. referred to correct jurisdiction.
WAR044503	2/23/2024	2/23/2024	Pollution hotline (phone, web, app): spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue.	Yes, No Notice Required	1210 38th ave e	Seattle	98112	47.630147	-122.283735	Sediment/soil: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue.	Construction activity: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue.	Not applicable: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue.	Referred to other agency or department: spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue.	spu spill response received report of construction site pumping stormwater from a site. pumped water was carrying sediment down alley as well as scouring it. drainage in area is combined. issue will likely be referred to another spu group to address issues. not impacting the ms4, not a water quality issue.
WAR044503	11/19/2024	11/19/2024	Pollution hotline (phone, web, app): report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out.	Yes, Notified Ecology	10712 aurora ave n	Seattle	98133	47.707554	-122.344397	Fuel and/or vehicle related fluids: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out.	Other accident/spill: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out.	Not applicable: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out.	Clean-up: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out., Other: report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out.	report of coolant leaking from vactor truck into a sandbox. an additional vector will be brought in to pump out the sandbox. material captured in ms4 sandbox, and pumped out.
WAR044503	7/10/2024	7/10/2024	Direct report to your staff: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck.	Yes, No Notice Required	east marginal way s & 1st ave s	Seattle	98108	47.548270	-122.334319	Firefighting foam: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck.	Other: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck.	Not applicable: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck.	nfa_spills, Other: spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck.	spill response investigation of a fire fighting response at right of way on the shoulder of east marginal way s. fire fighting water with fire fighting foam is assumed to have impacted ms4, wsdot drainage, and king county sanitary sewer with an unknown amount impacting the duwamish river. no pollution was observed within the river or ms4 however. a few thousand gallons of contaminated water ponding on the right of way was recovered by dwwrc with a vactor truck.
WAR044503	1/23/2024	1/23/2024	Pollution hotline (phone, web, app): gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4.	Yes, No Notice Required	1240 ne 127th st	Seattle	98125	47.721862	-122.313819	Fuel and/or vehicle related fluids: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4.	Intentional dumping: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4.	Not applicable: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4.	Clean-up: gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4.	gas tank on a toyota tacoma was drilled and gasoline was spilled to the paved street shoulder. spu performed clean up and left waste with vehicle owner to dispose. no impact to drainage or ms4.
WAR044503	6/18/2024	6/18/2024	Staff referral: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck.	Yes, Notified Ecology	7242 seaview ave nw	Seattle	98117	47.682135	-122.403613	Sewage/septage/pet waste/human waste: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck.	Intentional dumping: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck.	Not applicable: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck.	Clean-up: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck., Other: approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck.	Complaint. approx 5gal of rv wastewater spilled to pavement and ms4. work order created for crews to pump cb, and clean curb line with eductor truck.
WAR044503	12/20/2024	12/20/2024	Pollution hotline (phone, web, app): report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4.	Yes, No Notice Required	860 terry ave n	Seattle	98109	47.627591	-122.336623	Other: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4.	Unconfirmed, unspecified, or not identified: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4.	Not applicable: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4.	Other: report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4.	report of diesel spill on lake union. investigated and found no known source. determined it was not from the ms4.
WAR044503	11/5/2024	11/5/2024	Pollution hotline (phone, web, app): vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4.	Yes, Notified Ecology	44th ave s / s bateman st	Seattle	98118	0	0	Fuel and/or vehicle related fluids: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4.	Intentional dumping: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4.	Not applicable: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4.	Clean-up: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4., Other: vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4.	vehicle's fuel tank drilled (vandalism) spilling one gallon onto pavement, one gallon into inlet and three gallons spilling into combined sanitary line. gasoline was cleaned up by spill responders. no impact to ms4.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/8/2024	2/8/2024	Pollution hotline (phone, web, app): spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper.	Yes, No Notice Required	450 ne 100th st	Seattle	98125	47.701781	-122.323526	Solid waste/trash: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper.	Intentional dumping: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper.	Not applicable: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper.	Clean-up: spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper.	spu spills responded to report of paper garbage in water quality channel tied to thornton creek. investigations revealed report to be correct. spu maintains this channel. work order was created to clean this paper. no erts submitted given relatively small quantity of paper.
WAR044503	7/16/2024	7/16/2024	Pollution hotline (phone, web, app): received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Yes, No Notice Required	1748 nw market st	Seattle	98107	0	0	Food-related oil/grease: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Other accident/spill: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Not applicable: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	Clean-up: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary. , Education/technical assistance: received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.	received a report about a grease spill in an alley. site visit confirmed grease was spilled and tracked throughout the alley. no drain impact. responsible party cleaned and disposed of the waste. no further action is necessary.
WAR044503	10/31/2024	10/31/2024	Pollution hotline (phone, web, app): motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil.	Yes, Notified Ecology	nw 50th st & 15th ave nw	Seattle	98107	47.665098	-122.376388	Fuel and/or vehicle related fluids: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil.	Vehicle collision: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil.	Not applicable: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil.	Clean-up: motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil.	motor vehicle accident going northbound on 15th cause 1 quart of motor oil to spill into catch basin attached to ms4. boom applied. no downstream impacts. maintenance hole before outfall did not contain signs of oil.
WAR044503	5/23/2024	5/23/2024	Pollution hotline (phone, web, app): one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4.	Yes, Notified Ecology	1401 alaskan way	Seattle	98101	0	0	Other: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4.	Other accident/spill: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4.	Not applicable: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4.	Clean-up: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4. , Other: one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4.	one quart of diesel accidentally spilled onto pavement. a small amount entered waterway. spiller cleaned up sidewalk and placed boom into water to collect diesel. no impact to ms4.
WAR044503	11/15/2024	11/15/2024	Pollution hotline (phone, web, app): report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin.	Yes, No Notice Required	6924 rainier ave s	Seattle	98118	47.540046	-122.270822	Fuel and/or vehicle related fluids: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin.	Other: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin.	Not applicable: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin.	Clean-up: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin. , Education/technical assistance: report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin.	report of used cooking oil spilled on a sidewalk/parking lot. investigation found used motor oil had spilled from a neighboring business, and was cleaned. 1/4 cup of oil reached ms4 catch basin and was recovered; no oil left the catch basin.
WAR044503	6/12/2024	6/12/2024	Pollution hotline (phone, web, app): report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted.	Yes, Notified Ecology	1137 29th ave s	Seattle	98144	47.592365	-122.295722	Sewage/septage/pet waste/human waste: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted.	Unconfirmed, unspecified, or not identified: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted.	Not applicable: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted.	Clean-up: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted. , Other: report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted.	Complaint. report of sewage smell in private cb. cb tested positive for ammonia. frc investigated and no issues with city mainline. issue is due to dogs and possible homeless individuals urinating in cb. ms4 impacted.
WAR044503	1/4/2024	1/4/2024	Pollution hotline (phone, web, app): sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted.	Yes, No Notice Required	7124 s 115th st	Seattle	98178	47.499874	-122.244480	Fuel and/or vehicle related fluids: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted.	Vehicle-related business: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted.	Not applicable: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted.	Clean-up: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted. , Other: sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted.	sheen of an unknown source and unknown amount impacted roadway and one cb. cleaned cb using on-hand material. ms4 impacted.
WAR044503	2/11/2024	2/11/2024	Pollution hotline (phone, web, app): spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts	Yes, No Notice Required	9748 densmore ave n	Seattle	98103	47.700955	-122.337403	Fuel and/or vehicle related fluids: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts	Other accident/spill: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts	Not applicable: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts	Clean-up: spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts	spu spills responded to self-report of leaked oil to sidewalk. spu cleaned minor spill. no impact to ms4. no erts
WAR044503	4/21/2024	4/21/2024	Pollution hotline (phone, web, app): a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcpw were notified of the incident.	Yes, Notified Ecology	1307 n 43rd st	Seattle	98103	47.659034	-122.341807	Sewage/septage/pet waste/human waste: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcpw were notified of the incident.	Other accident/spill: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcpw were notified of the incident.	Not applicable: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcpw were notified of the incident.	Clean-up: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcpw were notified of the incident. , Other: a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcpw were notified of the incident.	a side sewer discharged a few gallons of sewage to a cb in the ms4. sewage did not make it passed the cb. spu crews got the discharge to stop and submitted a work order to have the cb cleaned. ecology and kcpw were notified of the incident.
WAR044503	3/14/2024	3/14/2024	ERTS referral: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4.	Yes, Notified Ecology	1001 sw klickitat way	Seattle	98134	47.569860	-122.348970	Other: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4.	Other accident/spill: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4.	Not applicable: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4.	Other: report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4.	Complaint. report of hose breaking causing an undetermined amount of turbid water to enter into the duwamish river resulting in high ntus. no impact to ms4.
WAR044503	10/16/2024	10/16/2024	MS4 inspection or screening: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing.	Yes, Notified Ecology	35th ave s / alaska st	Seattle		47.560752	-122.288832	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing.	Unconfirmed, unspecified, or not identified: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing.	Not applicable: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing.	Other: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing. , Other: spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing.	Complaint. spu dry weather screening identified trigger level potassium concentration in the ms4. a source tracing investigation found the issue is not ongoing.
WAR044503	5/31/2024	5/31/2024	Pollution hotline (phone, web, app): truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste.	Yes, No Notice Required	1811 38th ave e	Seattle	98112	47.635025	-122.284386	Fuel and/or vehicle related fluids: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste.	Vehicle-related business: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste.	Not applicable: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste.	Clean-up: truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste.	truck leaked hydraulic oil to the ground. no drains impacted. spiller cleaned up and disposed of waste.
WAR044503	8/6/2024	8/6/2024	MS4 inspection or screening: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified.	Yes, Notified Ecology	s warsaw st & 39th ave s	Seattle	98118	47.543182	-122.283302	Other: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified.	Unconfirmed, unspecified, or not identified: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified.	Not applicable: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified.	Other: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified. , Other: spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified.	Complaint. spu identified trigger level potassium test results in the ms4. follow up source tracing investigation found the issue was not on going and a source was not able to be identified.
WAR044503	6/27/2024	6/27/2024	Pollution hotline (phone, web, app): water to water diesel release. no impact to ms4. nrc previously notified. nfa.	Yes, Notified Ecology	water body ballard locks	Seattle		47.665814	-122.398974	Fuel and/or vehicle related fluids: water to water diesel release. no impact to ms4. nrc previously notified. nfa.	Unconfirmed, unspecified, or not identified: water to water diesel release. no impact to ms4. nrc previously notified. nfa. , Other accident/spill: water to water diesel release. no impact to ms4. nrc previously notified. nfa.	Not applicable: water to water diesel release. no impact to ms4. nrc previously notified. nfa.	Referred to other agency or department: water to water diesel release. no impact to ms4. nrc previously notified. nfa.	water to water diesel release. no impact to ms4. nrc previously notified. nfa.
WAR044503	2/12/2024	2/12/2024	Pollution hotline (phone, web, app): report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4.	Yes, No Notice Required	9416 1st ave ne	Seattle	98115	47.697502	-122.327619	Other: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4.	Other: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4.	Not applicable: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4.	Other: report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4.	Complaint. report of muddy water being pumped on property from adjacent property. adjacent property has flooding issues. no impact to ms4.
WAR044503	12/16/2024	12/16/2024	ERTS referral: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills	Yes, Notified Ecology	3409 stone way n	Seattle	98103	47.648950	-122.343126	Other: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills	Unconfirmed, unspecified, or not identified: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills	Not applicable: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills	Clean-up: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills. , Education/technical assistance: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills. , Other: report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills.	Complaint. report of green liquid determined to be tracing dye. case referred to orc / dww field crew for follow-up. nfa_spills

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	9/9/2024	9/9/2024	nfa_spills ERTS referral: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler.	Yes, Notified Ecology	925 seneca st	Seattle	98101	47.609857	-122.327750	Fuel and/or vehicle related fluids: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler.	Vehicle-related business: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler.	Not applicable: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler.	Other: spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler.	Complaint. spill of motor oil from illegal dumping into a dumpster. spill to pavement only. cleaned up by waste hauler.
WAR044503	12/23/2024	12/23/2024	Pollution hotline (phone, web, app): report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4.	Yes, No Notice Required	3902 s ferdinand st	Seattle	98118	47.558067	-122.283202	Fuel and/or vehicle related fluids: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4.	Intentional dumping: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4.	Not applicable: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4.	Clean-up: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4. . Other: report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4.	Complaint. report of fuel in cb due to fuel tank being drilled. cb not impacted. no impact to ms4.
WAR044503	4/30/2024	4/30/2024	Pollution hotline (phone, web, app): two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted.	Yes, Notified Ecology	m l king jr way s / s massachusetts st	Seattle		47.588311	-122.298061	Fuel and/or vehicle related fluids: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. Fuel and/or vehicle related fluids: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted.	Vehicle collision: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted.	Not applicable: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted.	Clean-up: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted. . Other: two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted.	two car accident caused about four gallons of auto fluids to spill onto pavement. only a few ounces entered into cb. cleaned pavement and cb with spill pads and granular (sdot). ms4 impacted.
WAR044503	3/14/2024	3/14/2024	Pollution hotline (phone, web, app): sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired.	Yes, Notified Ecology	western ave / union st	Seattle		47.607362	-122.340226	Sewage/septage/pet waste/human waste: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired.	Other accident/spill: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired.	Not applicable: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired.	Clean-up: sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired.	sewer exfiltrated an spu combined sewer mainline and entered a series of Seattle city light underground vaults. eventually sewage was pumped out via a sump pump in one of the scl vaults via a curb weep to western ave where sewage then flowed until it reached an inlet that connects to the ms4. outfall is to elliot bay. spu crews coordinated with scl to pump down vaults and set up a pump and bypass until combined mainline can be repaired.
WAR044503	12/6/2024	12/6/2024	Pollution hotline (phone, web, app): rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program.	Yes, Notified Ecology	8400 10th ave sw	Seattle	98106	46.807974	-127.390431	Sewage/septage/pet waste/human waste: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program.	Intentional dumping: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program.	Not applicable: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program.	Clean-up: rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program.	rv leaking sewage to pavement. waste disposed of to the sanitary sewer. clients referred to the rv wastewater program.
WAR044503	8/27/2024	8/27/2024	Pollution hotline (phone, web, app): spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties.	Yes, Notified Ecology	i-5 hwy & james st	Seattle	98104	47.607048	-122.330224	Fuel and/or vehicle related fluids: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties.	Vehicle collision: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties.	Not applicable: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties.	Clean-up: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties. . Other: spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties.	spu spill responders dispatched to report of diesel spill from mva on i-5. dept. of ecology had responsible party mitigate spill on i-5. spu source traced ms4 lines tied to wsdot lines from freeway. no observable diesel in ms4. however, diesel sheen was observed at outfall. doe and spu placed hydrophobic booms to collect sheen. erts was filled by other parties.
WAR044503	5/1/2024	5/1/2024	Direct report to your staff: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted.	Yes, No Notice Required	nesbit ave n / n 88th st	Seattle		47.692372	-122.343478	Fuel and/or vehicle related fluids: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted.	Intentional dumping: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted.	Not applicable: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted.	Clean-up: spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted.	Complaint. spu spill response received report of illegal oil dumping near catch basin. hydrophobic booms placed in catch basin to mitigate oil. pollution trap in place. no evidence of oil leaving catch basin; downstream main line did not have oil. erts submitted.
WAR044503	8/30/2024	8/30/2024	Pollution hotline (phone, web, app): spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified	Yes, No Notice Required	boylston ave / e pine st	Seattle		47.615230	-122.323426	Other: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified	Unconfirmed, unspecified, or not identified: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified	Not applicable: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified	Clean-up: spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified	spill of latex paint to pavement. no drain involvement. spu cleaned up all liquid paint and made a referral to sdot. no source identified
WAR044503	1/31/2024	1/31/2024	ERTS referral: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume.	Yes, Notified Ecology	1801 18th ave sw	Seattle	98134	47.586026	-122.353148	Sewage/septage/pet waste/human waste: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume.	Other accident/spill: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume.	Not applicable: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume.	Clean-up: customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume.	customer reported blockage in spu mainline but there was confusion whether this was sewage or stormwater. spu spill responder clarified that this was sewage and had the dwr crew dispatched. dwr cleared the blockage and returned system to operational. spu did not witness the overflow so no estimate of volume was possible. customer did provide photos that showed the sso so it is logged as an sso without volume.
WAR044503	4/25/2024	4/25/2024	ERTS referral: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property. parks cleaned affected catch basin. no evidence that receiving water body was impacted.	Yes, Notified Ecology	1000 ne 135th st	Seattle	98125	47.728586	-122.316635	Fuel and/or vehicle related fluids: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property. parks cleaned affected catch basin. no evidence that receiving water body was impacted.	Other accident/spill: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property. parks cleaned affected catch basin. no evidence that receiving water body was impacted.	Not applicable: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property. parks cleaned affected catch basin. no evidence that receiving water body was impacted.	Clean-up: spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property. parks cleaned affected catch basin. no evidence that receiving water body was impacted.	Complaint. spu spill response received erts 730455 notifying that gas spill occurred on Seattle parks property. parks cleaned affected catch basin. no evidence that receiving water body was impacted.
WAR044503	2/5/2024	2/5/2024	Pollution hotline (phone, web, app): report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents.	Yes, Notified Ecology	1st ave nw / nw 85th st	Seattle		47.690609	-122.357992	Fuel and/or vehicle related fluids: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents.	Unconfirmed, unspecified, or not identified: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents.	Not applicable: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents.	Clean-up: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents. . Other: report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents.	report of sheen in the roadway. spu observed sheen in the row impacting pavement, combined sewer storm drains, an ms4 storm drain, and confirmed no downstream impact. cleanup of ms4 drain by spu with on hand absorbents.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	5/20/2024	5/20/2024	ERTS referral: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4.	Yes, Notified Ecology	4224 university way ne	Seattle	98105	47.659101	-122.313008	Food-related oil/grease: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4.	Other accident/spill: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4.	Not applicable: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4.	Referred to other agency or department: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4. , Other: report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4.	report of cooking oil spilled in alleyway. referred to sdot and solid waste. no impact to ms4.
WAR044503	2/2/2024	2/2/2024	Pollution hotline (phone, web, app): spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private.	Yes, Notified Ecology	5300 24th ave nw	Seattle	98107	47.666541	-122.387565	Fuel and/or vehicle related fluids: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private.	Construction activity: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private.	Not applicable: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private.	Clean-up: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. , Education/technical assistance: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private. , Other: spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private.	spill of diesel to pavement and a storm drain from a generator related to a city construction project. cleanup completed by the responsible contractor. infrastructure maps show the affected storm drain is private.
WAR044503	4/9/2024	4/9/2024	Pollution hotline (phone, web, app): used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24.	Yes, Notified Ecology	4139 university way ne	Seattle	98105	47.657969	-122.313509	Food-related oil/grease: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. , Other: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24.	Other accident/spill: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24.	Not applicable: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24.	Clean-up: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24. , Education/technical assistance: used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24.	used cooking oil spilled but did not make it to drains. cleaned up with on hand materials. found out bin was abandoned and worked with vendors to remove bin. bin removed 4/29/24.
WAR044503	2/23/2024	2/23/2024	Pollution hotline (phone, web, app): spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill.	Yes, Notified Ecology	3711 ne 44th st	Seattle	98105	47.660344	-122.287639	Fuel and/or vehicle related fluids: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill.	Intentional dumping: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill.	Not applicable: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill.	Clean-up: spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill.	spu spill response received a report of oil in street. spu investigated and found gasoline spill of approximately 3 gallons impacting concrete right of way. ms4 not impacted. no drains were impacted. granular absorbent was placed and a sdot sweeper clean spill. erts submitted given area of gasoline spill.
WAR044503	4/2/2024	4/2/2024	Pollution hotline (phone, web, app): spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills.	Yes, No Notice Required	6th ave s / s massachusetts st	Seattle	98119	47.588249	-122.325965	Fuel and/or vehicle related fluids: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills.	Vehicle collision: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills.	Not applicable: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills.	Clean-up: spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills.	spill of motor oil to pavement during rv towing. no drain impacts. cleaned by spills.
WAR044503	2/9/2024	2/9/2024	Pollution hotline (phone, web, app): received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc.	Yes, Notified Ecology	1177 fairview ave e	Seattle	98102	47.630806	-122.329192	Fuel and/or vehicle related fluids: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc.	Intentional dumping: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc.	Not applicable: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc.	Clean-up: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc. , Education/technical assistance: received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc.	received a report of sheen in lake union. during the site visit we located a private cb that outfalls to the lake that had gas in it. property management team hired a contractor to clean the cb. i reported it to ecology and nrc.
WAR044503	8/12/2024	8/12/2024	Pollution hotline (phone, web, app): gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa.	Yes, Notified Ecology	33rd pl s / s holly pl	Seattle		47.542169	-122.290090	Fuel and/or vehicle related fluids: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa.	Intentional dumping: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa.	Not applicable: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa.	Clean-up: gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa.	gasoline found in ms4 from vandalism. removed product from cb with sectional booms. ms4 impacted but sheen not found at outfall. nfa.
WAR044503	7/17/2024	7/17/2024	ERTS referral: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4.	Yes, Notified Ecology	1829 10th ave w	Seattle	98119	47.635587	-122.370641	Other: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4.	Vehicle-related business: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4.	Not applicable: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4.	Clean-up: commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4.	Complaint. commerial vehicle had a mechanical malfunction causing one gallon of hydraulic fluid to spill onto pavement. responsible party had already cleaned up spilled material upon my arrival. no impact to ms4.
WAR044503	9/26/2024	9/26/2024	Pollution hotline (phone, web, app): vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley.	Yes, Notified Ecology	847 hiawatha pl s	Seattle	98144	47.594847	-122.309627	Fuel and/or vehicle related fluids: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley.	Other accident/spill: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley.	Not applicable: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley.	Clean-up: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley. , Education/technical assistance: vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley.	vehicle accident caused a truck tank of diesel to spill. diesel entered a single cb on the ms4. the responsible party hired a contractor to clean the cb and alley.
WAR044503	4/8/2024	4/8/2024	Pollution hotline (phone, web, app): hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa.	Yes, Notified Ecology	1008 ne 105th st	Seattle	98125	47.705118	-122.317291	Other: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa.	Other accident/spill: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa.	Not applicable: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa.	Other: hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa.	hydraulic spill from recology from 4/4. it was cleaned up day of and did not reach drains. ms4 impacted but no drain involvement. nfa.
WAR044503	3/22/2024	3/22/2024	Pollution hotline (phone, web, app): report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery.	Yes, Notified Ecology	2700 airport way s	Seattle	98134	47.579183	-122.320757	Fuel and/or vehicle related fluids: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery.	Unconfirmed, unspecified, or not identified: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery.	Not applicable: report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery.	Report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery.	report of sheen impacting a drain at a city facility. spu investigation found unknown sheen impact to pavement and an ms4 drain. no active source was determined and on hand absorbents were used for recovery.
WAR044503	8/29/2024	8/29/2024	Direct report to your staff: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal.	Yes, No Notice Required	4760 denver ave s	Seattle	98134	0	0	Solid waste/trash: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal.	Intentional dumping: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal.	Not applicable: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal.	Referred to other agency or department: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal. , Other: two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal.	Complaint. two large piles of garbage and debris dumped on city property near cb. submitted into to illegal dumping for removal.
WAR044503	11/17/2024	11/17/2024	Pollution hotline (phone, web, app): report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin.	Yes, Notified Ecology	1600 pike pl	Seattle	98101	47.609696	-122.341779	Other: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin.	Other accident/spill: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin.	Not applicable: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin.	Clean-up: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin. , Other: report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin.	report of 20 gallons of spilled milk with 1 gallon entering a drain. responsible party hired a contractor to clean the impacted catch basin. ms4 catch basin impacted, material did not leave the catch basin.
WAR044503	2/1/2024	2/1/2024	ERTS referral: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved.	Yes, Notified Ecology	1519 alaskan way s	Seattle	98134	47.590172	-122.338008	Fuel and/or vehicle related fluids: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved.	Vehicle-related business: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved.	Not applicable: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved.	Clean-up: motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved.	Complaint. motor oil leak from a staff personal vehicle on uscg property impacting pavement and a separated storm drain. containment and cleanup by uscg with no impact to the city ms4. vehicle was towed offsite and the problem is resolved.
WAR044503	8/19/2024	8/19/2024	Pollution hotline (phone, web, app): commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Yes, Notified Ecology	1630 43rd ave e	Seattle	98112	47.634287	-122.276526	Fuel and/or vehicle related fluids: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Vehicle-related business: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Not applicable: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	Clean-up: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4. , Other: commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.	commerial vehicle spilled one gallon of hydraulic fluid onto pavement and cleaned it up. no impact to ms4.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	3/15/2024	3/15/2024	Pollution hotline (phone, web, app): pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4.	Yes, No Notice Required	n 38th st / winslow pl n	Seattle		47.652744	-122.346615	Other: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4.	Vehicle collision: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4.	Not applicable: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4.	Other: pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4.	pickup pulling smaller trailer and trailer overturned spilled approximately 45 gallons of hydroseed onto roadway. sdot used sweeper for cleanup. no impact to ms4.
WAR044503	5/10/2024	5/10/2024	Pollution hotline (phone, web, app): arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4.	Yes, No Notice Required	rainier ave s / 57th ave s	Seattle		47.520263	-122.261593	Fuel and/or vehicle related fluids: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4.	Vehicle collision: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4.	Not applicable: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4.	Clean-up: arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4.	arrived at location of motor vehicle accident. one cup of hydraulic fluid spilled onto pavement which was cleaned up using oil pads. no impact to ms4.
WAR044503	7/17/2024	7/17/2024	ERTS referral: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4.	Yes, Notified Ecology	853 lake washington blvd s	Seattle	98144	47.595165	-122.289109	Fuel and/or vehicle related fluids: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4.	Other accident/spill: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4.	Not applicable: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4.	Clean-up: report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4.	Complaint. report of motor oil spilled onto pavement. found three cups spilled and i cleaned up using granular absorbent. no impact to ms4.
WAR044503	8/2/2024	8/2/2024	Direct report to your staff: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party.	Yes, No Notice Required	8850 9th ave sw	Seattle	98106	47.523193	-122.346471	Sewage/septage/pet waste/human waste: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party.	Vehicle-related business: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party.	Not applicable: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party.	Clean-up: investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party.	Complaint. investigation of rv dumping verified leak of sewage into containment buckets. buckets had overflowed and spilled to pavement. area cleaned and buckets of sewage disposed of to sanitary sewer. technical assistance provided to responsible party.
WAR044503	7/1/2024	7/1/2024	Pollution hotline (phone, web, app): found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa.	Yes, Notified Ecology	406 broadway e	Seattle	98102	47.622248	-122.320603	Food-related oil/grease: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa.	Other accident/spill: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa.	Not applicable: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa.	Clean-up: found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa.	found used cooking oil spilling out of used cooking oil container. spell was cleaned and contractor was hired to emergency pump container no impact to ms4. business inspection completed nfa.
WAR044503	11/14/2024	11/14/2024	Pollution hotline (phone, web, app): received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste.	Yes, Notified Ecology	3919 18th ave w	Seattle	98119	47.655611	-122.380643	Fuel and/or vehicle related fluids: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste.	Vehicle-related business: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste.	Not applicable: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste.	Clean-up: received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste.	received a spill report about gasoline entering a catch basin on port property. product did not make it to the water body. responsible party is cleaning and disposing of the waste.
WAR044503	1/25/2024	1/25/2024	Pollution hotline (phone, web, app): report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb.	Yes, Notified Ecology	s hanford st / 27th ave s	Seattle		47.575085	-122.298277	Fuel and/or vehicle related fluids: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb.	Vehicle-related business: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb.	Not applicable: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb.	Clean-up: report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb.	Complaint. report of oil sheen in row from unknown source. cleaned with onhand material. sheen entered into a cb.
WAR044503	7/1/2024	7/1/2024	Pollution hotline (phone, web, app): sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl.	Yes, Notified Ecology	2710 ne 105th st	Seattle	98125	47.704918	-122.298314	Sediment/soil: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl.	Construction activity: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl.	Not applicable: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl.	Education/technical assistance: sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl.	sediment reported in thomton creek. found a creek remediation project at thomton and willow creek. referral to ecology, sdot and oma cescl.
WAR044503	8/16/2024	8/16/2024	Pollution hotline (phone, web, app): report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program.	Yes, No Notice Required	n 94th st / stone ave n	Seattle		47.697071	-122.341914	Sewage/septage/pet waste/human waste: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program.	Intentional dumping: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program.	Not applicable: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program.	Clean-up: report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program.	Complaint. report of sewage discharge from an rv encampment. investigation found no active discharge. vehicle occupant stated that he had a leak but is has been repaired. he also stated that he is served by the spu rv wastewater program.
WAR044503	6/21/2024	6/21/2024	Pollution hotline (phone, web, app): received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology.	Yes, Notified Ecology	m l king jr way s & s henderson st	Seattle	98118	47.523245	-122.279219	Fuel and/or vehicle related fluids: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology.	Vehicle collision: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology.	Not applicable: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology.	Other: received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology.	received a report about automotive fluids entering a drain from a car accident. pavement was cleaned by sdot, a very small unrecoverable amount of coolant made it to the ms4. i notified ecology.
WAR044503	7/10/2024	7/10/2024	Pollution hotline (phone, web, app): received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary.	Yes, Notified Ecology	5958 east marginal way s	Seattle	98134	47.549189	-122.334802	Other: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary.	Construction activity: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary.	Not applicable: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary.	Other: received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary.	received a spill page about pipes coming from a building discharging water. site visit confirmed water was leaving the building, and entering a private drainage system that outfalls directly to the duwamish river. after speaking with a few key people, it was concluded that their sprinkler system is being worked on. no further action is necessary.
WAR044503	2/5/2024	2/5/2024	Pollution hotline (phone, web, app): self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Yes, Notified Ecology	golden gardens dr nw / loyal ave nw	Seattle		47.693734	-122.399329	Fuel and/or vehicle related fluids: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Vehicle-related business: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Not applicable: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact.	Clean-up: self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact.	self report of a coolant leak to pavement from a leaking waste collection truck. cleanup completed by the responsible party. no ms4 impact.
WAR044503	10/3/2024	10/3/2024	Pollution hotline (phone, web, app): report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact.	Yes, No Notice Required	east marginal way s & s horton st	Seattle	98134	47.574387	-122.339944	Fuel and/or vehicle related fluids: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact.	Unconfirmed, unspecified, or not identified: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact.	Not applicable: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact.	Clean-up: report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact.	report of spilled transmission fluid to pavement. no responsible party was able to be determined and cleanup was completed by spu with on hand supplies. no ms4 drain impact.
WAR044503	2/21/2024	2/21/2024	Pollution hotline (phone, web, app): hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste.	Yes, No Notice Required	130 s kenyon st	Seattle	98108	47.533212	-122.330306	Fuel and/or vehicle related fluids: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste.	Other: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste.	Not applicable: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste.	Clean-up: hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste.	hydraulic line on compactor at south transfer station broke & spilled approximately 50 gallons. no drains impacted & sts staff cleaned & disposed of waste.
WAR044503	12/23/2024	12/23/2024	Pollution hotline (phone, web, app): report of construction company pumping muddy water from property after each rain event. no impact to ms4.	Yes, No Notice Required	9547 wallingford ave n	Seattle	98103	47.699190	-122.336810	Other: report of construction company pumping muddy water from property after each rain event. no impact to ms4.	Other: report of construction company pumping muddy water from property after each rain event. no impact to ms4.	Not applicable: report of construction company pumping muddy water from property after each rain event. no impact to ms4.	Referred to other agency or department: report of construction company pumping muddy water from property after each rain event. no impact to ms4.	report of construction company pumping muddy water from property after each rain event. no impact to ms4.

Permit number	Date incident discovered	Date beginning response	How was the incident discovered or reported to you	Discharge to MS4	Street Address or Intersection	City	Zip	Latitude	Longitude	Pollutants Identified	Source or Cause	Source tracing approach(es) used	Correction/elimination methods used	Field notes, explanations, and/or other comments
WAR044503	2/2/2024	2/2/2024	Pollution hotline (phone, web, app): report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair.	Yes, Notified Ecology	1700 sturgus ave s	Seattle	98144	47.588313	-122.311296	Sewage/septage/pet waste/human waste: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair.	Other accident/spill: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair.	Not applicable: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair.	Clean-up: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair., Other: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair., Other: report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair.	report of surfacing sewage due to a private side sewer problem which impacted an ms4 drain. spu crews implemented bmps to redirect to the combined sewer. spu side sewer program will work with the property owner to coordinate a repair.